



Vlaanderen  
is maritiem



# Notices to Mariners

AGENCY  
MARITIME and  
COASTAL SERVICES

No. 21  
8 OCTOBER 2020  
NOTICES: 294 - 301  
[www.flemishhydrography.be](http://www.flemishhydrography.be)

Published by: Administrator General Nathalie Balcaen  
IAA Maritime and Coastal Services (MSC)  
Brussels 2020

© Flemish Government

Compiled by: Coastal Division - Flemish Hydrography  
Vrijhavenstraat 3  
8400 Oostende  
Belgium

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MSC – Coastal Division – Flemish Hydrography".

© Photography: Coastal Division Design:  
Printing Office Lowyck Ostend

**This is a free translation of the official "Berichten aan Zeevarenden, nr. 21 jaargang 2020"**  
**In case of dispute the Dutch text is the only valid copy.**

General guidelines concerning the use of the Belgian NtM are described in the annual edition no. 1 of the Belgian Notices to Mariners.

Positions are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

Depths (in metres): are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

Heights (in metres): drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions, bearings, leading lines and light sectors (in degrees) are true reckoned from seawards.

**AGENCY**  
**MARITIME and**  
**COASTAL SERVICES**

The Coastal Division is ISO9001  
and ISO14001 certified (version  
2015).

**FRANCE****2020-21/294 VLAAMSE BANKENROUTE - EAST DYCK - BUOY ODAS EOLOS - CHART CORRECTION**

**Charts:** 102 (INT 1480), D11

Insert in position 51°09,96'N 002°22,27'E:

yellow ODAS buoy "EOLOS" with light character Fl(5)Y.20s, yellow lying cross as topmark and AIS.

Source: SHOM AAN 20 40 32

**BELGIUM****2020-21/295 LOWER SEA SCHELDT - REDE ANTWERPEN - FERRY SINT-ANNA - CHART CORRECTION****Charts:** 104/03, 106 (INT 1478)

Add a ferry (INT1 M50) in magenta in positions:

- 51°13,35'N 004°23,77'E

- 51°13,46'N 004°23,56'E

Add magenta text "Sint-Annaveer" in position 51°13,48'N 004°23,32'E.

Source: Vlaamse Hydrografie

**2020-21/296 PORT OF ANTWERPEN - WAASLANDHAVEN - ZUIDELIJK INSTEKDOEK - DAMAGE JETTY CANCELLED**

NtM 2020-20/290(T) is cancelled.

**Charts:** 106 (INT 1478), 104/04

Source: Haven Antwerpen NPA 20/412 annulatie

**2020-21/297 PORT OF ANTWERPEN - 3DE HAVENDOK - MOORING PROHIBITION CANCELLED****Charts:** 104/03, 106 (INT 1478)

Mooring prohibition in the 3de Havendok at quay 182, 5m before and 5m after mooring post 85.5, has been cancelled.

Source: Haven Antwerpen NPA 12/013 annulatie

**2020-21/298 PORT OF ANTWERPEN - ALBERTDOK - MOORING PROHIBITION QUAY 182-198A****Charts:** 104/03, 104/04, 106 (INT 1478)

There is a permanent mooring prohibition in the Albertdok at quay 182-198A between mooring post 85 ½ and 141 ½. The mooring prohibition is for all shipping, except vessels with the permission of BNFV and PoA.

Source: Haven Antwerpen NPA 20/442

**2020-21/299(T) PORT OF ANTWERPEN - AMERIKADOK - NOORDKASTEELBRUG - SOUTHERN UNDERPASSAGE BLOCKED****Charts:** 104/03, 104/04, 106 (INT 1478)

Southern underpassage of Noordkasteelbrug is blocked for all shipping until 13 november 2020, longer or shorter in duration depending on the progress of the works.

2 temporary buoys with radar reflector and signalisation are placed in front of the fixed span.

The shipping is asked:

- to call up the Noordkasteelbrug in time (VHF - channel 62)

- to follow the signaling at the bridge strictly

Source: Haven Antwerpen NPA 20/459

**THE NETHERLANDS****2020-21/300 CANAL GHENT-TERNEUZEN - TERNEUZEN - WORKS NEW LOCK TERNEUZEN**

**Charts:** 105/10, 104/09, 105/09

Due to the construction of the new lock "Nieuwe Sluis Terneuzen", multiple works will be in progress until 2022.

Source: NLHO NiM 2020-40/302(T)

**2020-21/301 CANAL GHENT-TERNEUZEN - TERNEUZEN - WEST-BUITENHAVEN - LIGHTING MODIFIED - CORRECTION OF CHARTS AND LIST OF LIGHT**

**Charts:** 105/10

**List of Lights**

Delete:

F.Y in position 51°20,24'N 003°48,49'E (Int. no B0249.5 - nat. no 0685.1)

F.Y in position 51°20,17'N 003°48,55'E (Int. no B0249.8 - nat. no 0685.2)

F.Y in position 51°20,09'N 003°48,61'E (Int. no B0250.3 - nat. no 0685.3)

Add:

F.Y in position 51°20,25'N 003°48,75'E (Int. no B0249.5 - nat. no 0685.1)

F.Y in position 51°20,17'N 003°48,76'E (Int. no B0249.8 - nat. no 0685.2)

F.Y in position 51°20,02'N 003°48,85'E (Int. no B0250.3 - nat. no 0685.3)

Source: NLHO NiM 2020-40/303

**MARITIME SAFETY INFORMATION (MSI)  
in force**

**MSI > 19/664 TSS - WESTHINDER**

TRIPODE WITH HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-22.867 N 002-27.162 E UNMARKED. SHIPPING IS REQUESTED NOT TO FISH AND TO PASS AT A SAFE DISTANCE .

**MSI > 19/780 TSS - WESTHINDER**

WESTHINDER MEASURING POLE, 51-23.31 N 002-26.26 E. LIGHT UNLIT .

**LB > 20/039 PORT OF OOSTENDE**

WATERBOND ACTIVITIES AT THE PIERHEADS OF THE HARBOR OF OOSTENDE . IN THE VICINITY OF THE HALVE MAAN. SHIPPING IS REQUESTED TO PASS WITH REDUCED SPEED IN ORDER TO AVOID EXCESSIVE WAVES.

**LB > 20/046 APPROACH OOSTENDE**

LIGHTBUOY H18, 51-17.43 N 002-51.73 E. TEMPORARILY REMOVED .

**MSI > 20/283 BLIGHBANK - THORNTONBANK**

LIGHTBUOY VLIZ, 51-34.80 N 002-59.59 E. TEMPORARILY REMOVED .

**MSI > 20/342 OOSTDYCK - KWINTE**

OOSTDYCK ANCHORAGE. M/V LISA. ANCHOR LOST IN POS 51-19.41 N 002-37.43 E.

**MSI > 20/421 DE PANNE - OOSTENDE**

SPECIAL PURPOSE BUOY O, 51-14.28 N 002-52.09 E. TEMPORARILY REMOVED .

**MSI > 20/439 OOSTENDE - ZEEBRUGGE**

UNDERWATER PIPELINE AND FLOATING PIPELINE ESTABLISHED BETWEEN POSITIONS 51-15,47 N 002-58,40 E AND 51-15,79 N 002-58,14 E MARKED BY CARDINAL BUOY 'DC1'. SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH ABOVE THIS PIPELINE AND TO PASS CLEAR OF IT

**MSI > 20/442 TSS - NOORDHINDER SOUTH**

FISHING VESSEL DROPPED AIRCRAFT ORDNANCE. IN POS 51°32,019 N - 002°24,28 E. SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY..

**MSI > 20/525 BE EEZ**

EXPLOSIVE IN POS 51°- 25,58 N 002°- 31,46 E. SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY..

**MSI > 20/528 BE EEZ**

EXERCISE MINES TEMPORARY LAID OUT. ON 14 SEP 2020. IN THE FOLLOWING POSITIONS :

51-27.387 N 002-43.012 E

51-27.799 N 002-42.455 E

51-28.148 N 002-43.114 E

51-27.736 N 002-43.672 E

SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THESE POSITIONS.

**MSI > 20/558 TSS - WESTHINDER**

M/V WANDELAAR. ANCHOR LOST IN POS 51-19.314 N 002-47.342 E.

**MSI > 20/569 SCHEUR**

LIGHTBUOY S4, 51-25.03 N 003-02.85 E. TEMPORARILY REMOVED .

**MSI > 20/570 VAARGEUL 1**

LIGHTBUOY VG1, 51-25.03 N 002-49.05 E. TEMPORARILY REMOVED .