



Vlaanderen
is maritiem

Notices to Mariners

No. 2024-07
28 MARCH 2024
NOTICES: 109 - 112

www.flemishhydrography.be

Published by:

Administrator General Nathalie Balcaen
IAA Maritime and Coastal Services (MCS) - Brussels
2024

Compiled by:

Coastal Division - Flemish Hydrography
Vrijhavenstraat 3 - 8400 Ostend - Belgium

© Flemish Government

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MCS – Coastal Division – Flemish Hydrography".

This is a free translation of the official "Berichten aan Zeevarenden, nr. 2024-07"
In case of dispute the Dutch text is the only valid copy.

General guidelines concerning the use of the Belgian NtM are described in the annual edition no. 01 of the Belgian Notices to Mariners.

Positions:

are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

Depths (in metres):

are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

Heights (in metres):

drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions, bearings, leading lines and light sectors (in degrees):

are true reckoned from seawards.

BELGIUM

2024-07/109 FAIRY-NOORDHINDER - BUOYS

NtM 2023-14/169(T) is cancelled.

Charts: D11

Source: MRCC MSI 156/24, MSI 157/24, MSI 158/24

2024-07/110 FAIRY-NOORDHINDER - BUOYS

Charts: D11

Insert:

- Buoy ELI-W, west cardinal pillar, Q(9)15s in position 51°31,59'N 002°28,55'E
- Buoy ELI-N, north cardinal pillar, Q in position 51°32,53'N 002°29,69'E
- Buoy ELI-S, south cardinal pillar, Q(6)+LFl. 15s in position 51°30,87'N 002°30,06'E
- Buoy ELI-E, east cardinal pillar, VQ(3)5s in position 51°31,82'N 002°31,21'E

Source: MRCC MSI 177/24, MSI 178/24, MSI 180/24, MSI 181/24, Elia

2024-07/111 WINDFARMS - FAIRY - BATHYMETRY

Charts: 101 (INT 1474), 102 (INT 1480), D11

D11, 102 (INT 1480):

Delete:

- Sounding 9,9 in position 51°26,56'N 002°19,22'E

Insert:

- Sounding 9,1 in position 51°26,42'N 002°19,39'E, extend 10 m depth contour to the southeast

D11, 101 (INT 1474):

Delete:

- Sounding 15,3 in position 51°36,08'N 002°52,37'E
- Sounding 15,3 in position 51°36,72'N 002°54,05'E
- Sounding 16,5 in position 51°36,94'N 002°55,04'E

Insert:

- Sounding 14,7 in position 51°36,08'N 002°52'64'E
- Sounding 13,5 in position 51°36,50'N 002°54,17'E
- Sounding 14,7 in position 51°37,03'N 002°54,97'E
- Sounding 7,4 in position 51°32,39'N 002°57,73'E, extend 10 m depth contour to the west

Source: Vlaamse Hydrografie

THE NETHERLANDS**2024-07/112 KANAAL GENT-TERNEUZEN - TERNEUZEN - BUOY**

Charts: 104/09, 105/10

Move:

- Buoy NST-A from position 51°19,96'N 003°48,09'E to position 51°19,96'N 003°48,91'E

Source: NLHO

MARITIME SAFETY INFORMATION (MSI)
in force

LB > 22/013 DE PANNE-OOSTENDE

DANGEROUS OBSTACLE ON THE SEABED BUOY STONE AND CHAIN LOST IN POS 51-10.28 N 002-44.92 E

MSI > 22/209 WIELINGEN

MOW 3 MEASURING POLE, 51-23.38 N 003-11.92 E RACON: INACTIVE

MSI > 22/252 TSS-WESTHINDER

UNDERWATER OBSTACLE IN POS 51-25.086 N 002-35.246 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE ANCHORING AND FISHING ARE PROHIBITED

LB > 23/023 APPROACH OOSTENDE

OOSTENDE HIGH LEADINGLIGHT 143°, 51-13.63 N 002-56.10 E LIGHT UNRELIABLE

MSI > 23/108 TSS-WESTHINDER

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23.14 N 002-28.52 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/189 SEAAREA (COAST)

ZINKERLEIDING RAVERSIJDE UITGELEGD TUSSEN STRAND EN 51-13.294 N 002-51.385 E GEMARKEERD MET NOORDKARDINALE BOEI 'JDN' ZINKERLEIDING LOMBARDSIJDE UITGELEGD TUSSEN STRAND EN POS 51-10.17 N 002-45.01 E GEMARKEERD MET NOORDKARDINALE BOEI 'DC1'

MSI > 23/309 BE EEZ

ANCHOR LOST IN POS 51-21.383 N 003-07.011 E

MSI > 23/367 TSS-WESTHINDER

DANGEROUS OBSTACLES ON THE SEABED IN THE FOLLOWING AREA: 51 - 27 - 79 N 002 - 28 - 06 E 51 - 27 - 15 N 002 - 29 - 65 E 51 - 30 - 09 N 002 - 33 - 13 E 51 - 31 - 63 N 002 - 31 - 01 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 23/431 TSS-WESTHINDER

LIGHTBUOY A-S, 51-21.15 N 002-36.92 E LIGHT UNLIT

LB > 24/004 OUTER PORT

LIGHTBUOY ZA2, 51-21.08 N 003-11.93 E LIGHT UNRELIABLE

MSI > 24/010 VLAKTE VAN DE RAAN

LIGHTBUOY WK14, 51-22.11 N 003-15.72 E TEMPORARILY REMOVED

MSI > 24/041 TSS-OFF NOORDHINDER

LIGHTBUOY OHR1, 51-38.02 N 002-47.15 E LIGHT UNLIT

MSI > 24/115 BE EEZ

AN UNPROTECTED CABLE IS ON THE SEABED BETWEEN THE FOLLOWING COORDINATES 51-28.44 N - 003-2.31 E 51-28.34 N - 003-2.26 E 51-28.09 N - 003-3.59 E 51-28.17 N - 003-3.63 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE PROHIBITED TO ANCHOR NOR TO FISH IN THIS VICINITY

MSI > 24/119 BE EEZ

OOSTDIJCK ANCHORAGE M/V CL ATLAS ANCHOR AND CHAIN LOST IN POS 51-20.26 N 002-35.20 E

MSI > 24/130 VAARGEUL 1

LIGHTBUOY VG2, 51-25.95 N 002-48.12 E LIGHT UNLIT