

LIST OF CORRECTIONS

Chart	List of Lights
	Edition 2016
Updated up to and including NtM	11 / 2022
	26 May 2022

The last version of these corrections are available on
www.agentschapmdk.be/en/publications

2016

07/121 - 09/145 - 09/150 - 09/152 - 10/154 - 10/158 - 10/163 - 11/172 -
 14/194 - 14/195 - 14/196 - 14/197 - 14/201 - 14/203 - 15/210 - 18/226 -
 18/232 - 18/236 - 18/238 - 19/249 - 20/256 - 20/257 - 20/261 - 21/267 -
 21/268 - 21/274 - 22/284 - 23/291 - 25/298 - 25/305 - 25/306 - 25/307 -
 26/311

2017

03/061 - 04/073 - 04/075 - 04/079 - 07/112 - 08/121 - 08/130 - 11/158 -
 11/159 - 11/160 - 11/161 - 11/162 - 11/163 - 11/164 - 11/165 - 11/168 -
 12/173 - 12/177 - 12/178 - 13/179 - 13/184 - 14/189 - 14/194 - 15/196 -
 15/199 - 17/213 - 17/218 - 18/219 - 18/221 - 18/222 - 18/225 - 19/231 -
 19/232 - 21/252 - 22/262 - 22/272

2018

03/059 - 04/070 - 04/071 - 04/073 - 04/074 - 06/080 - 06/084 - 09/116 -
 09/117 - 09/125 - 11/147 - 12/152 - 12/154 - 13/159 - 13/166 - 13/168 -
 14/177 - 18/207 - 18/209 - 19/220 - 20/225 - 20/237 - 21/250 - 21/251 -
 22/252 - 22/259 - 23/260 - 23/261 - 24/269

2019

03/064 - 03/070 - 04/080 - 06/110 - 09/146 - 11/170 - 11/175 - 13/190 -
 15/209 - 15/210 - 15/215 - 16/228 - 17/234 - 17/236 - 19/251 - 26/318

2020

03/107 - 08/152 - 08/157 - 08/158 - 09/164 - 10/178 - 10/181 - 11/203 -
 13/228 - 14/248 - 15/253 - 15/254 - 16/260 (P) - 17/262 - 17/268 - 19/286 -
 21/301 - 26/346

2021

02/089 - 03/103 - 04/105 - 04/107 - 04/110 - 07/144 - 07/145 - 07/147 -
 10/168 - 10/169 - 10/181 - 14/204 - 15/208 - 19/229 - 19/243 - 20/242 -
 20/245 - 21/252 - 21/254 - 23/265 - 24/268 - 24/269 - 26/277 - 26/285 -
 26/286

2022

02/084 - 02/100 - 02/102 - 04/112 - 04/113 - 05/118 - 05/120 - 05/121 -
06/127 - 06/130 - 08/150 - 08/151 - 09/159 - 10/168

2016

2016-07/121 IMO ROUTE - WESTHINDER - VICINITY MEASURING POLE "WESTHINDER" - INSTRUMENTS - CORRECTION OF CHARTS AND LIST OF LIGHTS

BaZ 2015-12/157(T) is cancelled.

Delete:

- Wave recorder buoy with lettering aKust35 in position 51°22,86'N 002°26,35'E (Belg. LL 0028.1)

Insert:

- Wave recorder buoy with lettering aKust1 (yellow spherical with light character Fl(5)Y.20s and radar reflector) in position 51°22,89'N 002°26,22'E.
- Special marking buoy HD27 (yellow conical with light character Fl.Y.5s, radar reflector and yellow lying cross as topmark) in position 51°22,85'N 002°26,17'E.

The following special marking buoys remain:

- H11 in position 51°22,91'N 002°26,43'E
- H12 in position 51°22,95'N 002°26,16'E

2016-09/145 APPROACH WESTERN SCHELDT - VAARGEUL 1 - BUOY ESTABLISHED AND REPLACEMENT WAVE RECORDER BUOY - CORRECTION OF CHARTS AND LIST OF LIGHTS

On charts D11, 102 (INT1480), 101 (INT1474):

Delete:

The wave recorder buoy with lettering aKust32 in position 51°24,97'N 002°49,13'E.

Insert:

Wave recorder buoy with lettering aKust3 in position: 51°24,97'N 002°49,13'E.
(yellow spherical with light character Fl(5)Y.20s and radar reflector);

Special marking buoy HD1 in position 51°24,96'N 002°49,25'E
(yellow conical buoy with light character Fl.Y.5s and lying cross as topmark).

In List of Lights:

Delete:

The wave recorder buoy "Akkaert" in position 51°24,97'N 002°49,13'E
(Belg. LL 0063.1).

2016-09/150 WESTERN SCHELDT - VARIOUS PLACES - BUOYAGE PARALLEL ROUTES - CORRECTION OF CHARTS AND LIST OF LIGHTS

The buoyage of the parallel routes (fietspaden) as being a part of the main fairway in relation with BaZ no. 2016-09/141 is changed as following.

Sheet 104/10:

Pas van Borssele:

Delete buoys FB 1 and FB 3.

Sheet 104/09:

Pas van Borssele:

Renumber the following buoyage:

FB 5 becomes F9
FB 7 becomes F11
FB 9 becomes F13
FB 11 becomes FPvT

New parallel route (fietspad) near port of Terneuzen:

Insert a yellow buoy in following positions

F14 51°21,68'N 003°46,77'E
F16 51°21,39'N 003°47,68'E
F18 51°21,01'N 003°48,86'E
F24 51°21,20'N 003°51,84'E
F26 51°21,45'N 003°53,08'E
F28 51°21,77'N 003°53,84'E
F28A 51°22,21'N 003°54,79'E

Insert a red spar buoy 20A in position 51°20,91'N 3°50,00'E.

Renumber the following buoyage:

WPT2 becomes F20
WPT4 becomes F20A
WPT6 becomes F22
FP2 becomes F28B
FP4 becomes F30
FP6 becomes F32
FP8 becomes F34
FP1 becomes F31
FP3 becomes F33
FP5 becomes F35
FP7 becomes F37

Sheet 104/08:

Parallel route (fietspad) Zuidergat:

Delete buoys FZ1 and FZ2 (nat. no. 0791).

Insert a yellow buoy in following positions

F42 51°25,67'N 004°01,96'E
F47 51°25,98'N 004°00,08'E

Renumber the following buoyage:

FZ3 becomes F49
FZ5 becomes F51
FZ7 becomes F53
FZ9 becomes F53A
FZ11 becomes F55
FZ4 becomes F42A
FZ6 becomes F44
FZ8 becomes F46
FZ10 becomes F48
FZ12 becomes F48A

Sheet 104/07:

Parallel route (fietspad) Zuidergat:

Renumber the following buoyage:

FZ11	becomes	F55
FZ6	becomes	F44
FZ8	becomes	F46
FZ10	becomes	F48
FZ12	becomes	F48A

Parallel route (fietspad) above Valkenisse incl. changes in the lateral marking:

Delete buoy SvV18.

Modify the following buoyage:

The red lateral light buoy SvV16 into a South cardinal light buoy SvV16 (nat. no. 0802.2)

The South cardinal light buoy FM-SvV (nat. no. 0802.5) into a yellow buoy F60

Renumber FM2 into F62.

Sheet 104/06:

Parallel route (fietspad) above Valkenisse incl. changes in the lateral marking:

Renumber the following buoyage:

FM4	becomes	F64A
FM6	becomes	F64B
FM8	becomes	F66
64A	becomes	F64B

Insert the following light buoys:

64A Iso.R.8s	51°22,72'N	004°08,89'E	(nat. no. 0854.1)
69A Iso.G.4s	51°22,74'N	004°09,59'E	(nat. no. 0856.1)

Parallel route (fietspad) above Saeftinghe:

Renumber the following buoyage:

S1	becomes	F81
S3	becomes	F81A
S5	becomes	F83
S7	becomes	F83A
S9	becomes	F83B

Sheet 104/05:

Parallel route (fietspad) above Saeftinghe:

Renumber the following buoyage:

S1	becomes	F81
S3	becomes	F81A
S5	becomes	F83
S7	becomes	F83A
S9	becomes	F83B
S11	becomes	F85
S13	becomes	F85A

Chart 106 (INT1478) panel A:

Parallel route (fietspad) above Valkenisse incl. changes in the lateral marking:

Delete buoy SvV18.

Modify the following buoyage:

- The red lateral light buoy SvV16 into a South cardinal light buoy SvV16
- The South cardinal light buoy FM-SvV into a yellow buoy F60

Renumber the following buoyage:

FM2	becomes	F62
FM4	becomes	F64A
FM6	becomes	F64B
FM8	becomes	F66
64A	becomes	F64B

Parallel route (fietspad) above Saeftinghe:

Renumber the following buoyage:

S1	becomes	F81
S3	becomes	F81A
S5	becomes	F83
S7	becomes	F83A
S9	becomes	F83B
S11	becomes	F85
S13	becomes	F85A

Insert the following light buoys:

64A	Iso.R.8s	51°22,72'N	4°08,89'E	(nat. no. 0854.1)
69A	Iso.G.4s	51°22,74'N	4°09,59'E	(nat. no. 0856.1)

2016-09/152 WESTERN SCHELDT - EVERINGEN - GEUL VAN BAARLAND - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

BaZ 2016-06/117(T) is cancelled.

Following change of buoyage is performed:

Move

Buoy E7	to position	51°22,276'N	003°49,168'E	
Buoy E9	to position	51°22,049'N	003°49,930'E	
Light buoy E11	to position	51°21,808'N	003°50,839'E	(Belg.LL 0631.3)
Light buoy E13	to position	51°21,715'N	003°51,592'E	(Belg.LL 0631.2)
Buoy E19	to position	51°22,810'N	003°54,046'E	
Light buoy E10	to position	51°21,947'N	003°50,955'E	(Belg.LL 0632.1)
Light buoy E12	to position	51°21,947'N	003°51,623'E	(Belg.LL 0631.1)
Light buoy E14	to position	51°22,233'N	003°52,402'E	(Belg.LL 0633)

Move and renumber

Light buoy E15 (old E17)	to position	51°22,034'N	003°52,512'E	
(light character Q.G and Belg.LL 0632.3)				
Light buoy E17 (old E15)	to position	51°22,386'N	003°53,370'E	
(delete in the List of Lights: light with nat. no. 0633.2)				

New insert

Buoy E13A	in position	51°21,874'N	003°52,198'E	
-----------	-------------	-------------	--------------	--

2016-10/154 GENERAL NOTICE - NEW PUBLICATION

New edition of 2016 of the List of Lights.

The List of Lights edition 2016 is from now available in the hydrostore for the amount of 15 euro/piece.

For more information to buy this publication, consult www.vlaamsehydrografie.be and click on Hydrostore.

2016-10/158 COASTAL ROUTE - WAVE RECORDER BUOYS AKUST2 AND AKUST5 DEFINITELY REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

BaZ 2015-26/297(T) and 2015-26/299(T) are cancelled.

Delete:

Wave recorder buoy aKust2 in position 51°14,81'N 002°55,66'E (LL nat. no. 0439.1)

Wave recorder buoy aKust5 in position 51°18,99'N 003°06,10'E (LL nat. no. 0467.1)

2016-10/163 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - CORRECTION OF CHARTS AND LIST OF LIGHTS

BaZ 2016-02/070(T) is cancelled.

Following buoyage is moved:

Light buoy SvV11 to position	51°22,68'N	004°05,67'E	(LL nat. no. 0802.3)
Light buoy SvV13 to position	51°22,36'N	004°06,09'E	(LL nat. no. 0802.4)
Buoy SvV12 to position	51°22,67'N	004°05,94'E	
Light buoy SvV14 to position	51°22,51'N	004°06,20'E	(LL nat. no. 0802.1)
Light buoy SvV16 to position	51°22,40'N	004°06,44'E	(LL nat. no. 0802.2)
Buoy SvV18 to position	51°22,42'N	004°06,80'E	

2016-11/172 WESTERN SCHELDT - OVERLOOP VAN HANSWEERT - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

The following change of buoyage is performed:

Light buoy 41 is moved to position 51°24,71'N 003°57,91'E (LL nat. no. 0742)

2016-13/181 COASTAL ROUTE - OOSTENDE-ZEEBRUGGE - VICINITY MOW 1 - WAVE RECORDER BUOY AKUST13 REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete on charts and List of Lights:

Wave recorder buoy aKust13 in position 51°21,58'N 003°07,19'E.
(LL nat. no. 0122.1)

**2016-13/182 APPROACH WESTERN SCHELDT - WIELINGENPAS - VICINITY MOW 3 - WAVE
RECORDER BUOY AKUST26 REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete on charts and List of Lights:

Wave recorder buoy aKust26 in position 51°23,51'N 003°12,03'E.
(LL nat. no. 0130.2)

**2016-14/194 IMO ROUTE - WESTHINDER - LIGHT BUOY OD1 NEW POSITION -
CORRECTION OF CHART AND LIST OF LIGHTS**

Move: Light buoy **OD1** to new position 51°21,47'N 002°30,84'E.
(LL INT no. B0146.5 - nat. no. 0030.1)

**2016-14/195 IMO ROUTE - WESTHINDER - LIGHT BUOY OOSTDYCKBK REMOVED -
CORRECTION OF CHART AND LIST OF LIGHTS**

Delete: Light buoy **OostdyckBk** in position 51°21,38'N 002°31,12'E.
(LL INT no. B0146.8 - nat. no. 0030)

**2016-14/196 IMO ROUTE - WESTHINDER - LIGHT BUOY KBK2 REMOVED -
CORRECTION OF CHART AND LIST OF LIGHTS**

Delete: Light buoy **KBk2** in position 51°21,04'N 002°42,22'E.
(LL nat. no. 0036)

**2016-14/197 IMO ROUTE - WESTHINDER - LIGHT BUOY KBK NEW POSITION -
CORRECTION OF CHART AND LIST OF LIGHTS**

Move: Light buoy **KBk** to new position 51°21,04'N 002°42,22'E.
(LL INT no. B0070 - nat. no. 0037)

**2016-14/201 WESTERN SCHELDT - SCHAAR VAN SPIJKERPLAAT - CHANGE OF BUOYAGE -
CORRECTION OF CHART AND LIST OF LIGHTS**

Modify following buoyage:

Buoy "SS 5" in position 51°24,71'N 003°38,04'E:

Modify into a green spar buoy

Delete light on buoy "SS 5"

Delete national light no. 0574 in List of Lights

Buoy "SS 7" in position 51°24,85'N 003°38,72'E:

Modify into a green conical light buoy

Insert light on buoy "SS 7" with light character "Iso.G.8s"

Insert national light no. 0576 in List of Lights

**2016-14/203 WESTERN SCHELDT - SCHAAR VAN VALKENISSE -
CORRECTION OF CHART AND LIST OF LIGHTS**

BaZ 2016-10/163 is cancelled.

Move:

Light buoy SvV11 to position 51°22,68'N 004°05,67'E (LL nat. no. 0802.3)
Light buoy SvV13 to position 51°22,36'N 004°06,09'E (LL nat. no. 0802.4)
Buoy SvV12 to position 51°22,67'N 004°05,94'E
Light buoy SvV14 to position 51°22,51'N 004°06,20'E (LL nat. no. 0802.1)
Light buoy SvV16 to position 51°22,40'N 004°06,44'E (LL nat. no. 0802.2)

Delete:

Buoy SvV18.

**2016-15/210 APPROACH WESTERN SCHELDT - WIELINGEN -
YACHT HARBOUR CADZAND - CORRECTION OF LIST OF LIGHTS**

Yacht harbour Cadzand:

Insert light numbers to the new harbor lights:

- Western jetty - light in position 51°22,860'N 003°22,898'E:
Int. no. B0158 - nat. no. 0141
- Eastern jetty - light in position 51°22,823'N 003°22,920'E:
Int. no. B0157.5 - nat. no. 0141.1

**2016-18/226 APPROACH OOSTENDE - BUOY OOSTENDEBK-E -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Modify buoy "Oostendebank E" on charts and List of Lights as following:

National light no.: 0272

Lettering: OostendeBk-E

Position: 51°17,35'N 002°51,92'E

Starboard lateral buoy: green, conical with radar reflector

Light character: Fl.G.5s

Topmark: green cone with point upwards

**2016-18/232 CANAL GENT-TERNEUZEN - RIEME -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Move following buoys:

Rieme N to position 51°11,07'N 003°48,04'E (LL nat. no. 1323.1)

Rieme Z to position 51°10,83'N 003°47,88'E (LL nat. no. 1323.2)

Enlarge the anchorage area, bounded by the magenta dashed line with anchor symbol, to following positions:

51°11,07'N 003°48,04'E

51°10,83'N 003°47,88'E

51°10,85'N 003°47,80'E

51°11,09'N 003°47,97'E

**2016-18/236 WESTERN SCHELDT - SLOEHAVEN -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete:

Leading line 059° from position 51°27,32'N 003°40,62'E up to 51°28,12'N 003°42,74'E

The light Dir F.WRG & Al.WR + Al.WG in position 51°28,35'N 003°43,36'E (LL nat. no. 0604 - Int. no. B0206.21)

Mooring buoy in position 51°27,74'N 003°41,96'E

2016-18/238 WESTERN SCHELDT - SCHAAR VAN DE NOORD - BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Following change of buoyage is performed:

Move:

SN 1 to position 51°23,07'N 004°10,61'E

SN 3 to position 51°23,23'N 004°10,97'E

Delete:

yellow spar buoy SN 6

light buoy SN 4 (LL nat. no. 0875.3)

Insert:

yellow cylindrical buoy SN 6 in position 51°23,50'N 004°12,11'E with light character VQ.Y and LL nat. no. 0875.5

yellow spar buoy SN 4 in position 51°23,54'N 004°11,74'E

2016-19/249 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Following buoys are moved:

SvV 4 to position 51°24,39'N 004°03,80'E

SvV 6 to position 51°24,01'N 004°04,47'E

SvV 8 to position 51°23,61'N 004°05,15'E

SvV 10 to position 51°23,17'N 004°05,61'E

SvV 12 to position 51°22,74'N 004°05,86'E

SvV 14 to position 51°22,49'N 004°06,11'E

SvV 16 to position 51°22,38'N 004°06,40'E (Light no. 0802.2)

SvV 5 to position 51°23,85'N 004°04,26'E

SvV 7 to position 51°23,49'N 004°04,94'E

SvV 9 to position 51°23,14'N 004°05,36'E

SvV 13 to position 51°22,35'N 004°06,04'E (Light no. 0802.4)

**2016-20/256 APPROACH OOSTENDE - BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

The following buoys are fitted with a green cone with point upwards as topmark:

01 in position 51°15,73'N 002°53,41'E (LL nat. no. 0435.1)

03 in position 51°14,93'N 002°54,37'E (LL nat. no. 0435.3)

05 in position 51°14,53'N 002°54,92'E (LL nat. no. 0435.5)

The following buoy is fitted with a red cylinder as topmark:
06 in position 51°14,58'N 002°55,06'E (LL nat. no. 0435.6)

The following buoys are fitted with a radar reflector:
02 in position 51°15,83'N 002°53,61'E (LL nat. no. 0435.2)
04 in position 51°15,03'N 002°54,57'E (LL nat. no. 0435.4)

2016-20/257 PORT OF OOSTENDE - WESTERN HARBOUR LIGHT - CORRECTION OF LIST OF LIGHTS

Insert international light number B0095 at the western harbour light in position 51°14,44'N 002°54,96'E (nat no.: 0436.2).

2016-20/261 APPROACH ZEEBRUGGE - DAM NOORD - AKUST25 EN HD07 WITHDRAWN - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete the following buoys:
Wave recorder buoy aKust25 in position 51°21,41'N 003°10,27'E (Nat. LL no. 0469.1).
Marking buoy HD07 in position 51°21,46'N 003°10,24'E (Nat. LL no. 0469.2).

2016-21/267 FRANCE - VLAAMSEBANKENROUTE - BUOY "RUYTINGEN SE" - CORRECTION OF CHARTS AND LIST OF LIGHTS

Light buoy "Ruytingen SE" in position 51°09,20'E 002°08,92'E (LL nat. no. 0396)

Insert on charts:
A magenta circle with magenta text "AIS" (INT1 symbol S17.2).

Insert in the List of Lights:
Colum 8: AIS with MMSI no. 992271126.

Modify in the List of Lights:
Colum 5: replace height 4 by 6
Colum 6: replace range 3 by 4

2016-21/268 FRANCE - DYCKBANK - BUOY "DY3" - CORRECTION OF CHARTS AND LIST OF LIGHTS

Light buoy "DY3" in position 51°11,45'E 002°22,42'E (LL nat. no. 0256)

Insert on charts:
A magenta circle with magenta text "AIS" (INT1 symbol S17.2).

Insert in the List of Lights:
Colum 8: AIS with MMSI no. 992271118.

Modify in the List of Lights:
Colum 5: replace height 4 by 5

**2016-21/274 WESTERN SCHELDT - OOSTGAT-SARDIJNGEUL - BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

BaZ 2016-02/064(T) is cancelled.

Following change of buoyage is performed:

Delete:

Buoy "Westduin" in position 51°27,39'N 003°31,69'E.

Buoy "OG 10A" (Iso.R.2s) in position 51°27,81'N 003°31,27'E.

Move:

Buoy "OG-DL" to position 51°28,07'N 003°30,62'E (LL no. 0227).

Buoy "OG 19" to position 51°27,50'N 003°30,74'E (LL no. 0230).

Buoy "OG 14" to position 51°27,43'N 003°31,43'E (LL no. 0232).

Modify:

The light character of buoy "OG 12" in position 51°27,88'N 003°31,20'E into
"Iso.R.2s" (LL no. 0229).

Insert:

Red can buoy "OG 14A" with light character "Iso.R.4s" in position 51°27,27'N
003°31,66'E (LL no. 0232.1).

**2016-22/284 WESTERN SCHELDT - PAS VAN TERNEUZEN - BUOYAGE - CORRECTION OF
CHARTS AND LIST OF LIGHTS**

Modify on chart and List of Lights:

- buoy '15' in position 51°23,19'N 003°42,38'E: light character Iso.G.4s
(LL no. 0649).

- buoy '15a' in position 51°22,84'N 003°42,93'E: green conical with light
character VQ.G (LL no. 0650).

**2016-23/291 WESTERN SCHELDT - EVERINGEN - BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

E5 to position 51°22,71'N 003°47,80'E LL no. 0628

E-ZE to position 51°22,61'N 003°48,26'E

E7 to position 51°22,42'N 003°49,00'E

E10 to position 51°21,89'N 003°51,10'E LL no. 0632.1

E12 to position 51°21,90'N 003°51,65'E LL no. 0631.1

E16 to position 51°22,61'N 003°53,13'E LL no. 0632.2

E11 to position 51°21,76'N 003°50,94'E LL no. 0631.3

E13 to position 51°21,71'N 003°51,74'E LL no. 0631.2

E13A to position 51°21,83'N 003°52,36'E

E15 to position 51°22,05'N 003°52,73'E LL no. 0632.3

**2016-25/298 FRANCE - DYCKBANK - "BUOY DY1" -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Light buoy "DY1" in position 51°08,96'E 002°14,92'E (LL nat. no. 0252)

Insert on the charts:

A magenta circle with the magenta text "AIS" (INT1 symbol S17.2).

Insert in the List of Lights:

Column 8: AIS with MMSI no. 992271129.

Modify in the List of Lights:

Column 5: replace height 4 by 5

Column 6: replace range 3 by 4

**2016-25/305 WESTERN SCHELDT - VAARWATER LANGS HOOFDPLAAT - BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Insert on charts 101 (INT1474), 104/10:

Light (Iso.G.4s) on buoy 'VH 1' in position 51°23,17'N 003°37,10'E.

Insert in the List of Lights:

Green spar buoy VH1 in position 51°23,17'N 003°37,70'E with light character Iso.G.4 and Belgian light no. 0585.

**2016-25/306 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - CORRECTION OF CHARTS
AND LIST OF LIGHTS**

A shoal is found in the southern entrance of the Schaar van Valkenisse. The southern entrance seems to shift in its entirety to the western direction.

Move:

Buoy 58 to position 51°22,28'N	004°06,00'E	(LL no. 0847)
SvV 13 to position 51°22,36'N	004°05,98'E	(LL no. 0802.4)
SvV 16 to position 51°22,38'N	004°06,32'E	(LL no. 0802.2)

**2016-25/307 WESTERN SCHELDT - SCHAAR VAN DE NOORD - FAIRWAY RESTRICTION -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

BaZ 2016-22/286(T) is cancelled.

The shoal in the Schaar van de Noord has evolved, the depths in the Schaar van de Noord are strongly subject to modification due to natural phenomena and this fairway is extremely unstable and unreliable. Because of the instability and unreliability of this fairway, it is decided, after consultation and with immediate effect, to apply draught restrictions at the Schaar van de Noord.

The least depth for the Schaar van de Noord is on 11 November 2016: 13 dm referred to LAT.

Draught restriction Schaar van de Noord:

The draught restrictions are depending on the current water level Bath involving each vessel, because of the instability and unreliability of the fairway, to have a keel clearance of at least 6 dm. In other words, the maximum allowable draught on the basis of the current readings is the sum of

the current water level Bath referred to LAT +7 dm. The GNA can always orally adjust this formula through the traffic center Zandvliet.

Modify the buoyage:

Delete:

Light buoy SN 6 (LL no. 0875.5)

Buoy SN 11

Buoy SN 13

Move to position:

Buoy Alca-N 51°23,23'N 004°11,11'E (topmark: 2 black cones upwards)

Buoy SN 2 51°23,50'N 004°11,21'E (topmark: lying cross)

Buoy SN 4 51°23,50'N 004°11,85'E (topmark: lying cross)

Buoy SN 3 51°23,25'N 004°11,50'E (topmark: lying cross)

Light buoy SN 5 51°23,26'N 004°11,90'E (topmark: lying cross) (LL no. 0875.4)

Buoy SN 7 51°23,15'N 004°12,28'E (topmark: lying cross)

Buoy SN 9 51°22,89'N 004°12,58'E (topmark: lying cross)

Insert light on buoy:

SN 4 VQ.Y (LL no. 0875.3)

Alca-N Q.W (LL no. 0872.1)

Modify in the List of Lights:

insert:

"SN 4": 51°23,50'N 004°11,85'E, yellow can light buoy with light character VQ.Y and lying cross as topmark (LL no. 0875.3)

"Alca-N": 51°23,23'N 004°11,11'E, north-cardinal light buoy with light character Q.W (LL no. 0872.1)

Move: "SN 5" to position 51°23,26'N 004°11,90'E (LL no. 0875.4)

Delete: "SN 6" in position 51°23,50'N 004°12,11'E (LL no. 0875.5)

2016-26/311 WESTERN SCHELDT - VAARWATER LANGS HOOFDPLAAT - CORRECTION OF LIST OF LIGHTS

Modify in the List of Lights:

The position of the spar buoy VH1 is 51°23,17'N 003°37,10'E (LL no. 0585).

2017

2017-03/061 FAIRYBANK - BUOY "FAIRY OUEST" - CORRECTION OF CHARTS AND LIST OF LIGHTS

Light buoy "Fairy Ouest" in position 51°23,89'E 002°09,27'E
(LL Intern. No. A0993 - nat. no. 0012)

Insert on the charts:

A magenta circle with the magenta text "AIS" (INT1 symbol S17.2).

Insert in the List of Lights:

Column 8: AIS with MMSI no. 992271127.

2017-04/073 COASTAL ROUTE - DE PANNE-OOSTENDE - VICINITY NIEUWPOORT - WAVE RECORDER BUOY AKUST18 REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete on charts and List of Lights:

Wave recorder buoy aKust18 in position 51°09,65'N 002°41,43'E (LL nat. no. 0405.1).

2017-04/075 COASTAL ROUTE - DE PANNE-OOSTENDE - VICINITY RAVERSIJDE - WAVE RECORDER BUOY AKUST30 REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete on charts and List of Lights:

Wave recorder buoy aKust30 in position 51°13,23'N 002°52,17'E (LL nat. no. 0433).

2017-04/079 WESTERN SCHELDT - PAS VAN TERNEUZEN - DOW CHEMICAL - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete:

Pile and light Fl.R.3s in position 51°21,03'N 003°47,26'E (LL B0238.2 - 0680.1)

Replace light:

Fl.R.3s by Fl(3)R.10s in position 51°21,03'N 003°47,29'E (LL B0238.4 - 0680.2)

Insert:

Pile and light Fl(3)Y.10s in position 51°21,04'N 003°47,25'E (LL 0682.1)

Pile and light Fl(3)Y.10s in position 51°21,03'N 003°47,31'E (LL 0682.2)

2017-07/112 WESTERN SCHELDT - WALSOORDEN - OEVER LIGHT "OUDE HOOFD WALSOORDEN" - CORRECTION OF CHARTS AND LIST OF LIGHTS

The sector bearings of the oever light Oude Hoofd Walsoorden are modified as following (LL int. no. B0296 - nat. no. 0804):

- red: 132° to 175,5° (from the shore to the green light buoy 53A)
- white: 175,5° to 271° (over the red light buoy 48)
- green: 271° to 323,5° (over the red light buoy 50)
- white: 323,5° to 336,5° (over the green light buoy 59)
- red: 336,5° to 012° (over the shore)

2017-08/121 APPROACH WESTERN SCHELDT - WIELINGENPAS - BUOY NIPPON DEFINITELY MOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

BaZ 2017-07/109(T) is cancelled.

The south cardinal light buoy Nippon remains definitively moved in position 51°22,58'N 003°05,36'E.
(LL nat. no. 0118)

2017-08/130 WESTERN SCHELDT - EVERINGEN - BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move:

E7 to position 51°22,47'N 003°49,01'E
E9 to position 51°22,10'N 003°49,77'E
E11 to position 51°21,70'N 003°51,05'E LL no. 0631.3
E13 to position 51°21,69'N 003°51,77'E LL no. 0631.2
E15 to position 51°22,03'N 003°52,56'E LL no. 0632.3
E8 to position 51°22,30'N 003°50,22'E
E10 to position 51°21,87'N 003°51,04'E LL no. 0632.1
E12 to position 51°21,86'N 003°51,66'E LL no. 0631.1
E14 to position 51°22,18'N 003°52,39'E LL no. 0633

Insert:

E9A in position 51°21,85'N 003°50,39'E

Delete:

E13A

2017-11/158 BLIGHBANK - WIND FARM: BELWIND-NOBELWIND - LIGHTS AND FOG SIGNALS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete:

light with character Mo(U)Y.15s and fog signal with character Horn Mo(U)15s in positions:

Turbine BB F5	51°42,16'N	002°48,54'E	(light no. B0148 - 0025.1)
Turbine BB A5	51°40,46'N	002°47,52'E	(light no. B0148.2 - 0025.2)
Turbine BB A10	51°38,75'N	002°46,50'E	(light no. B0148.4 - 0025.3)
Turbine BB E5	51°39,83'N	002°48,72'E	(light no. B0148.8 - 0025.5)

Insert:

light with character Mo(U)Y.15s in position:

Turbine BB K09 51°39,18'N 002°45,98'E (light nr. 0025.9)

Insert:

light with character Mo(U)Y.15s and fog signal with character Horn Mo(U)15s in positions:

Turbine BB K10 51°38,94'N 002°46,05'E (light no. 0025.10)

Turbine BB K05 51°41,09'N 002°47,12'E (light no. 0025.11)

Turbine BB K02 51°42,68'N 002°48,06'E (light no. 0025.12)

Turbine BB J05 51°40,33'N 002°51,97'E (light no. 0025.13)

Turbine BB I07 51°38,81'N 002°50,03'E (light no. 0025.14)

Turbine BB G10 51°37,28'N 002°48,09'E (light no. 0025.15)

The following lights with character Mo(U)Y.15s and fog signal with character Horn Mo(U)15s remain in positions:

Turbine BB E10 51°38,13'N 002°47,70'E (light no. B0148.6 - 0025.4)

Turbine BB L01 51°41,30'N 002°50,19'E (light no. B0148.11 - 0025.6)

2017-11/159 TSS NOORDHINDER SOUTH - TSS OFF NOORDHINDER - LIGHT BUOY NHR-SE MOVED - CORRECTION OF LIST OF LIGHTS

Light buoy NHR-SE, in position 51°45,42'N 002°39,92'E, is removed.
(LL nat. no. 0024)

Special marking buoy **NHR-SE**, yellow pillar with light character Fl.Y.5s and a yellow lying cross as topmark, is established in position 51°43,44'N 002°37,21'E.
(LL nat. no. 0024)

2017-11/160 TSS OFF NOORDHINDER - LIGHT BUOY OHR7 ESTABLISHED - CORRECTION OF LIST OF LIGHTS

West cardinal buoy **OHR7**, with light character VQ(9)10s, is established in position 51°44,11'N 002°42,45'E.
(LL nat. no. 0024.1)

2017-11/161 TSS OFF NOORDHINDER - LIGHT BUOY OHR2 ESTABLISHED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Oost cardinal buoy **OHR2**, with light character VQ(3)5s, is established in position 51°37,20'N 002°38,41'E.
(LL nat. no. 0024.2)

2017-11/162 TSS OFF NOORDHINDER - LIGHT BUOY OHR1 ESTABLISHED - CORRECTION OF LIST OF LIGHTS

West cardinal buoy **OHR1**, with light character VQ(9)10s, is established in position 51°38,02'N 002°47,15'E. (LL nat. no. 0024.3)

**2017-11/163 APPROACH WESTERN SCHELDT - THORNTONBANK - LIGHT BUOY SW
THORNTON REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Light buoy SW Thornton, in position 51°30,95'N 002°50,92'E, is removed.
(LL nat. no. 0048)

**2017-11/164 WESTPIT - LIGHT BUOY WP2 ESTABLISHED -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Backboard red can light buoy **WP2**, with light character Iso.R.2s and a red cylinder as topmark, is established in position 51°30,51'N 003°02,68'E.
(LL nat. no. 0053.2)

**2017-11/165 WESTPIT - LIGHT BUOY WP1 ESTABLISHED -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Starboard green conical light buoy **WP1**, with light character Iso.G.2s, radar reflector and a green cone as topmark, is established in position 51°29,24'N 003°04,32'E.
(LL nat. no. 0053.1)

**2017-11/168 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - CORRECTION OF CHARTS
AND LIST OF LIGHTS**

Move:

SvV 12	to	51°22,72'N	004°05,84'E	
SvV 14	to	51°22,55'N	004°05,98'E	LL: nat.no. 0802.1
SvV 16	to	51°22,37'N	004°06,23'E	LL: nat.no. 0802.2

**2017-12/173 APPROACH WESTERN SCHELDT - VAARWATER SCHEUR - APPROACH WESTERN
SCHELDT MOW 4 - LIGHT BUOY REPLACED - CORRECTION OF CHARTS AND LIST OF
LIGHTS**

Light buoy HD4 in position 51°25,05'N 003°17,96'E, is replaced by a yellow conical special marking buoy HD7, with light character Fl.Y.5s, radar reflector and a yellow lying cross as topmark.

Delete in the List of Lights:

Light buoy HD4 (nat. no. 0102.1)

**2017-12/177 SCHELDT ESTUARY - WESTPIT - LIGHT BUOYS WP3, WP5 ESTABLISHED,
"WESTPIT" REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

The following light buoys are established:

- Lateral starboard buoy WP3, Iso.G.2s, in position 51°33,59'N 003°11,03'E
(nat. no. 0053.3)

- Lateral backboard buoy WP4, Iso.R.8s, in position 51°34,48'N 003°08,68'E (nat. no. 0053.4)

The following light buoy is removed:

- Safe water buoy Westpit in position 51°33,65'N 003°09,92'E (nat. no. 0180).

2017-12/178 SCHELDT ESTUARY - OOSTGAT - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete light buoy:

OG in 51°33,57'N 003°25,10'E (nat. no. 0201)

Insert light buoys:

OG 2 Q.R in 51°37,11'N 003°23,49'E (nat. no. 0187)
 OG 4 Iso.R.4s in 51°35,91'N 003°24,19'E (nat. no. 0195)
 OG 6 Q.R in 51°33,79'N 003°25,70'E (nat. no. 0197)

Move light buoys:

OG 1 Q.G to 51°36,37'N 003°20,73'E (nat. no. 0186)
 OG 3 Iso.G.4s to 51°35,24'N 003°22,40'E (nat. no. 0194)
 OG 5 Iso.G.8s to 51°34,10'N 003°23,88'E (nat. no. 0198)
 OG-DR Q(9)15s to 51°34,51'N 003°25,02'E (nat. no. 0199)

Modify name of (light) buoys:

OG 17A into OG 19 Iso.G.8s at 51°28,50'N 003°30,22'E (nat. no. 0222)
 OG 19 into OG 21 VQ.G at 51°27,50'N 003°30,74'E (nat. no. 0230)
 OG 21 into OG 23 Iso.G.4s at 51°27,05'N 003°31,53'E (nat. no. 0233)
 OG 2 into OG 8 VQ.R at 51°31,26'N 003°26,04'E (nat. no. 0213)
 OG 4 into OG 10 Iso.R.8s at 51°30,47'N 003°27,42'E (nat. no. 0215)
 OG 6 into OG 12 at 51°30,00'N 003°28,44'E
 OG 8 into OG 14 Iso.R.4s at 51°29,48'N 003°29,50'E (nat. no. 0220)
 OG 10 into OG 16 Iso.R.8s at 51°28,52'N 003°30,59'E (nat. no. 0223)
 OG 12 into OG 18 Iso.R.2s at 51°27,88'N 003°31,20'E (nat. no. 0229)
 OG 14 into OG 20 VQ.R at 51°27,43'N 003°31,43'E (nat. no. 0232)
 OG 14A into OG 22 Iso.R.4s at 51°27,27'N 003°31,66'E (nat. no. 0232.1)
 OG 16 into OG 24 Iso.R.8s at 51°27,13'N 003°32,36'E (nat. no. 0235)

2017-13/179 DUNKERQUE WESTERN HARBOUR - LEADING LIGHTS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Modify on D11:

The light character into Dir Fl.4s20M of the lights in position:
 51°01,67'N 002°11,92'E and 51°01,51'N 002°12,37'E.

Modify in the List of Lights:

front light (int. no. A1126 - nat. no. 0322.1) in position 51°01,67'N
 002°11,92'E and
 rear light (int. no. A1126.1 - nat. no. 0322.2) in position 51°01,51'N
 002°12,37'E:
 - Column 3: Dir Fl.W.4s
 - Column 6: 20

**2017-13/184 APPROACH WESTERN SCHELDT - OOSTGAT -
CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete light buoy:

OG-WG in 51°37,18'N 003°23,82'E (nat. no. 0190)

**2017-14/189 APPROACH WESTERN SCHELDT - VAARGEUL 1 - LIGHT BUOYS VG5 AND VG6
MOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Move:

Light buoy VG5 to position 51°24,73'N 002°56,78'E (nat. light no 0066)

Light buoy VG6 to position 51°25,22'N 002°56,24'E (nat. light no 0067)

**2017-14/194 APPROACH WESTERN SCHELDT - OOSTGAT -
CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Insert:

Measuring buoy DORA, yellow spherical, Fl(5)Y.20s, in position 51°37,13'N
003°23,62'E

Delete from the List of Lights:

Buoy DORA (nat. no 0191)

**2017-15/196 TSS - WESTHINDER - VICINITY BUOY KBk -
LIGHT BUOYS AND INSTRUMENTS - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Replace:

Wave recorder buoy aKust29 by wave recorder buoy aKust21 in position
51°20,95'N 002°42,44'E.

Insert:

Special marking buoy HD11, yellow conical with light character Fl.Y.5s and
a yellow lying cross as topmark, in position 51°20,96'N 002°42,51'E.

Delete from the List of Lights:

Wave recorder buoy aKust29 (nat. no. 0036.1)

**2017-15/199 CANAL GENT-TERNEUZEN - MOERVAART - LIGHT BUOYS AMT 1 AND AMT 2
REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete on chart and in the List of Lights:

the 2 red conical buoys in following positions:

AMT 1: 51°08,41'N 3°46,66'E (Belg. LL no.: 1329.1)

AMT 2: 51°08,33'N 3°47,01'E (Belg. LL no.: 1329.2)

2017-17/213 PORT OF ZEEBRUGGE - BUOYS ZW1 AND ZW3 MOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move:

Light buoy ZW1 to position 51°21,55'N 003°11,33'E (nat. no. 0476)

Light buoy ZW3 to position 51°21,55'N 003°11,21'E (nat. no. 0477.1)

2017-17/218 WESTERN SCHELDT - EVERINGEN - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

The following change of buoyage is performed:

move:

E11 to position 51°21,68'N 003°51,05'E LL no. 0631.3

E13 to position 51°21,66'N 003°51,74'E LL no. 0631.2

E15 to position 51°22,02'N 003°52,63'E LL no. 0632.3

E8 to position 51°22,33'N 003°50,07'E

E10 to position 51°21,81'N 003°51,08'E LL no. 0632.1

E12 to position 51°21,81'N 003°51,67'E LL no. 0631.1

E14 to position 51°22,15'N 003°52,49'E LL no. 0633

E16 to position 51°22,59'N 003°53,20'E LL no. 0632.2

Insert:

E8A in position 51°22,04'N 003°50,52'E Iso.R.4s LL no. 0631.4

2017-18/219 DYCKBANK - "BUOY DY2" - CORRECTION OF CHARTS AND LIST OF LIGHTS

Light buoy "DY2" in position 51°09,45'E 002°19,42'E (LL nat. no. 0254)

Insert on the charts:

A magenta circle with the magenta text "AIS" (INT1 symbol S17.2).

Insert in the List of Lights:

Column 8: AIS with MMSI no. 992271133.

Modify in the List of Lights:

Column 5: replace height 4 by 5

Column 6: replace range 3 by 4

2017-18/221 COASTAL ROUTE - OOSTENDE-ZEEBRUGGE - VICINITY BLANKENBERGE - LIGHT BUOY HBL REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete on the charts and in the List of Lights:

Light buoy HBL in position 51°19,03'N 003°06,09'E (LL nat. no. 0467.2).

**2017-18/222 PORT OF ZEEBRUGGE - FOG SIGNAL HEAD LEOPOLD II JETTY OUT OF USE
- CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete on the charts and in the List of Lights:

Fog signal "Horn(3+1)90s" at the head of the Leopold II jetty in position 51°20,86'N 003°12,18'E (see light: nat. no. 0496 - Int. no. B0122)

**2017-18/225 COASTAL ROUTE - ZEEBRUGGE-CADZAND -
LIGHT BUOY HD4 REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete on the charts and in the List of Lights:

Light buoy HD4 in position 51°21,75'N 003°17,45'E (LL nat. no. 0102.1).

**2017-19/231 COASTAL ROUTE - HAUT-FOND DE GRAVELINES - BUOY "H.F.
GRAVELINES" - CORRECTION OF CHART AND LIST OF LIGHTS**

Light buoy "H.F. Gravelines" in position 51°04,05'E 002°05,02'E (LL nat. no. 0294)

Insert on the charts:

A magenta circle with the magenta text "AIS" (INT1 symbol S17.2).

Insert in the List of Lights:

Column 8: AIS with MMSI no. 992271134.

Replace in the List of Lights:

Column 5: height 4 by 5

**2017-19/232 COASTAL ROUTE - DE PANNE-OOSTENDE - TRAPEGEER - LIGHT BUOYS
AKUST8 AND HD2 REMOVED - CORRECTION OF CHART AND LIST OF LIGHTS**

Remove from the charts and the List of Lights:

- Wave recorder buoy aKust8 in position 51°08,25'N 002°34,98'E (LL nat. no. 0390.1).
- Light buoy HD2 in position 51°08,31'N 002°34,86'E (LL nat. no. 0390.2).

**2017-21/252 COASTAL ROUTE - HAUT-FOND DE GRAVELINES -
BUOY "H.F. GRAVELINES" MOVED - CORRECTION OF CHART AND LIST OF LIGHTS**

Move:

Light buoy "H.F. Gravelines" to position 51°04,10'N 002°05,10'E.
(LL nat. no. 0294)

2017-22/262 PORT OF ZEEBRUGGE - WAVE RECORDER BUOY REPLACED - CORRECTION OF LIST OF LIGHTS

Replace:

Wave recorder buoy aKust12 by wave recorder buoy aKust97 in the same position 51°21,34'N 003°11,57'E.

Delete in the List of Lights:

Wave recorder buoy in position 51°21,34'N 003°11,57'E (nat. no. 0482.1).

2017-22/272 WESTERN SCHELDT - EVERINGEN - CORRECTION OF CHARTS AND LIST OF LIGHTS

The light characters of the buoys in Everingen are modified.

Insert:

E 7 in position 51°22,47'N 003°49,01'E LL no. 0630.1 Iso.G.4s

Modify:

E 11 in position 51°21,68'N	003°51,05'E	LL no. 0631.3	to Q.G
E 13 in position 51°21,66'N	003°51,74'E	LL no. 0631.2	to VQ.G
E 15 in position 51°22,02'N	003°52,63'E	LL no. 0632.3	to Iso.G.4s
E 10 in position 51°21,81'N	003°51,08'E	LL no. 0632.1	to Q.R
E 12 in position 51°21,81'N	003°51,67'E	LL no. 0631.1	to VQ.R
E 14 in position 51°22,15'N	003°52,49'E	LL no. 0633	to Iso.R.4s

2018

2018-03/059 APPROACH WESTERN SCHELDT - WESTPIT - LIGHT BUOY WP3 - CORRECTION OF CHARTS AND LIST OF LIGHTS

Modify:

the light character of the light buoy WP3, in position 51°33,59'N
003°11,03'E, into Iso.G.8s.
(nat. no. 0053.3)

2018-04/070 WESTERN SCHELDT - SCHAAR VAN SPIJKERPLAAT - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

NtM 2018-02/054(P) cancelled.

Move:

Buoy SS 2 to position 51°25,64'N 003°37,63'E insert cylindrical
topmark
Buoy SS 4 to position 51°25,23'N 003°37,82'E
Buoy SS 6 to position 51°25,30'N 003°38,85'E insert cylindrical
topmark
Lightbuoy SS 8 to position 51°25,26'N 003°39,83'E insert light Iso.R.4s
(LL no. 0577)
Lightbuoy SS 10 to position 51°24,89'N 003°40,84'E insert cylindrical
topmark
Lightbuoy SS 12 to position 51°24,36'N 003°41,43'E insert light Q.R (LL
no. 0577.1)
Lightbuoy SS 7 to position 51°24,90'N 003°38,73'E (LL no. 0576)
Lightbuoy SS 9 to position 51°24,95'N 003°39,66'E insert light Iso.G.4s
(LL no. 0576.1)
Lightbuoy SS 11 to position 51°24,60'N 003°40,52'E insert cylindrical
topmark and light Iso.G.8s (LL no. 0576.2)
Buoy SS 13 to position 51°24,18'N 003°41,08'E

Modify following buoys into spar buoys:

SS 6
SS 8
SS 10

2018-04/071 WESTERN SCHELDT - DREMPEL VAN BORSSELE - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

NtM 2018-02/055(P) cancelled.

Move:

Lightbuoy 13 to position 51°24,30'N 003°42,43'E Iso.G.8s (LL no.0644)
Lightbuoy PvT-SS to position 51°23,92'N 003°42,47'E VQ(3)5s (LL no.0646)
Buoy 13a to position 51°23,57'N 003°41,85'E
Lightbuoy PvT-E to position 51°24,42'N 003°42,73'E VQ(9)10s (LL no.0642)
Buoy WAAK to position 51°24,38'N 003°42,77'E

**2018-04/073 WESTERN SCHELDT - MIDDELGAT - CHANGE OF BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

NtM 2017-26/296(P) cancelled.

Delete:

Lightbuoy Middelgat in position 51°27,00'N 003°58,30'E (LL no 0640)

Move:

MG 8a to position 51°26,59'N 003°55,85'E

MG 12 to position 51°26,88'N 003°57,52'E

MG 14 to position 51°26,87'N 003°58,82'E modify into red can buoy with
light Oc(2)R.10s (LL no. 0639.1)

MG 11 to position 51°26,38'N 003°56,07'E (LL no. 0638)

MG 13 to position 51°26,65'N 003°56,41'E (LL no. 0638.1)

MG 15 to position 51°26,74'N 003°56,82'E modify into green conical buoy
with light Iso.G.8s (LL no. 0638.2)

MG 17 to position 51°26.73'N 003°57'47'E delete topmark

Insert:

MG 19 in position 51°26,72'N 003°58,30'E green conical buoy with light
Oc(2)G.10s (LL no. 0638.3)

**2018-04/074 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - CHANGE OF BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

NtM 2017-26/297(P) cancelled.

Move:

SvV 13 to position 51°22,36'N 004°05,94'E (LL no.0802.4)

SvV 16 to position 51°22,36'N 004°06,23'E (LL no.0802.2)

F 60 to position 51°22,37'N 004°06,76'E

Insert:

F 60A in position 51°22,43'N 004°07,26'E yellow spar buoy

**2018-06/080 APPROACH DUNKIRK EAST - BUOY DW30 MOVED - CORRECTION OF CHARTS
AND LIST OF LIGHTS**

Move:

Light buoy DW30 to position 51°04,150'N 002°20,235'E.
(LL no. 0358)

**2018-06/084 PORT OF OOSTENDE - WESTERN JETTY - WESTERN HARBOUR LIGHT
DEFINITIVELY REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS**

NtM 2017-21/256(T) is cancelled.

The western harbour light on the western jetty within the port of Oostende
in position 51°14,31'N 002°55,03'E is definitively removed.
(Int. no. B0094 - nat. no. 0436)

**2018-09/116 PORT OF ZEEBRUGGE - LNG-DOK - NAVIGATION LINES -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Insert the following navigation lines in the LNG-dok in Zeebrugge:

Navigation line 1: 168°

Upper (rear) light 1: 51°20,639'N 003°12,959'E (nat. no. 0519.1)

Lower (front) light 1: 51°20,666'N 003°12,949'E (nat. no. 0519.2)

Navigation line 2: 168°

Upper (rear) light 2: 51°20,696'N 003°13,077'E (nat. no.. 0519.3)

Lower (front) light 2: 51°20,715'N 003°13,070'E (nat. no.. 0519.4)

Navigation line 3: 348°

Upper (rear) light 3: 51°21,298'N 003°12,694'E (nat. no. 0519.5)

Lower (front) light 3: 51°21,272'N 003°12,703'E (nat. no. 0519.6)

The character of the lights is F.Bu and the range is 2 NM.

The height of the light source of the front lights is 12,7 m and of the rear lights 20,2 m.

The support of the lights is a metal mast alternately red, white painted.

**2018-09/117 PORT OF ZEEBRUGGE - LNG-DOK - LIGHT BUOY LNG2 ESTABLISHED -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Insert:

Special, yellow conical, marking buoy LNG2, with light character FL Y.5s, radar reflector and a yellow lying cross as topmark, in position 51°20,97'N 003°12,76'E (LL nat. no. 0520).

**2018-09/125 WESTERN SCHELDT - OVERLOOP VAN VALKENISSE - CHANGE OF BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete:

Buoy 69 A in position 51°22,74'N 004°09,59'E (LL no. 0856.1)

Insert:

Light on buoy MA 1 in position 51°22,59'N 004°09,44'E: Fl(2)Y.10s
(LL no.0856.2)

**2018-11/147 UPPER SEA SCHELDT - RUPELMONDE - BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Following buoys are removed:

TW in position 51°07,42'N 004°18,45'E (LL nat. no. 1085.1)

TW 1 in position 51°07,40'N 004°18,46'E (LL nat. no. 1085.2)

TW 2 in position 51°07,42'N 004°18,43'E (LL nat. no. 1085.3)

2017-12/152 LOWER SEA SCHELDT - DEURGANCKDOK - CORRECTION OF CHARTS AND LIST OF LIGHTS

Modify the light character of southern navigation line in the Deurganckdok as following:

Front light in position 51°16,78'N 004°15,00'E Oc.W.5s
(B0372.6 - nat. 0951.22)

Rear light in position 51°16,64'N 004°14,86'E Oc.W.5s
(B0372.601 - nat. 0951.21)

2018-12/154 WESTERN SCHELDT - VAARWATER LANGS HOOFDPLAAT - CORRECTION OF CHARTS AND LIST OF LIGHTS

Insert:

Light Iso.R.2s on buoy VH 2 in position 51°24,34'N 003°33,90'E (LL no. 0566).

2018-13/159 PORT OF ZEEBRUGGE - LNG-DOK - NAVIGATION LINES - LIST OF LIGHTS CORRECTION

Ref: NtM 2018-09/116.

Insert the following international light numbers:

Navigation line 1: 168°

Upper (rear) light 1: 51°20,639'N 003°12,959'E (nat. no. 0519.1): Int. no. B0126.81

Lower (front) light 1: 51°20,666'N 003°12,949'E (nat. no. 0519.2): Int. no. B0126.8

Navigation line 2: 168°

Upper (rear) light 2: 51°20,696'N 003°13,077'E (nat. no. 0519.3): Int. no. B0123.61

Lower (front) light 2: 51°20,715'N 003°13,070'E (nat. no. 0519.4): Int. no. B0123.6

Navigation line 3: 348°

Upper (rear) light 3: 51°21,298'N 003°12,694'E (nat. no. 0519.5): Int. no. B0127.41

Lower (front) light 3: 51°21,272'N 003°12,703'E (nat. no. 0519.6): Int. no. B0127.4

2018-13/166 UPPER SEA SCHELDT - RUPELMONDE - SECTORLIGHT GROENENDIJK - LIST OF LIGHTS CORRECTION

Insert in the List of Lights at p. 69:

Column 1: 1096 (INT. B0398.03)

Column 2: BORNEM-WINTAM Sectorlicht Groenendijk

Column 3: 51°07,33'N 4°17,87'E

Column 4: Oc.WRG.5s

Column 6: 4

Column 7: Zelfde paal als 1094.1

Column 8: 093,1-R-97,9-G-239,9-W-246,4-R-261-Ob-093,1

2018-13/168 WESTERN SCHELDT - MIDDELGAT - BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Insert:

Light "Iso.R.8s" on buoy "MG 12" in position 51°26,88'N 003°57,52'E (LL no. 0639.2).

2018-14/177 APPROACH WESTERN SCHELDT - WESTPIT - LIGHTBUOY WP4 MOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move:

the lightbuoy WP4 to position 51°34,38'N 003°08,68'E (LL nat. no. 0053.4).

2018-18/207 PORT OF ZEEBRUGGE - BRITTANNIADOK - FIXED LIGHTS AND TEMPORARY MARKING PILES WITH LIGHTS REMOVED - CORRECTION OF LIST OF LIGHTS

NtM 2017-19/234(T) is cancelled.

The works in the Brittanniadok are ended. The following temporary marking piles with lights are removed in the following positions:

51°20,595'N	003°12,906'E
51°20,592'N	003°12,960'E
51°20,636'N	003°13,046'E
51°20,543'N	003°12,976'E
51°20,556'N	003°13,037'E
51°20,576'N	003°13,092'E
51°20,523'N	003°12,741'E
51°20,538'N	003°12,732'E
51°20,552'N	003°12,740'E
51°20,536'N	003°12,951'E
51°20,530'N	003°12,972'E
51°20,516'N	003°12,974'E

The following fixed lights are removed in positions:

51°20,50'N	003°12,73'E, FR	(LL int. B0134.4 - nat. 0511.2)
51°20,51'N	003°12,77'E, FG	(LL int. B0134.5 - nat. 0511.3)
51°20,61'N	003°12,99'E, FR	(LL int. B0126.4 - nat. 0515.3)

2018-18/209 PORT OF ZEEBRUGGE - BRITTANNIADOK - NEW LIGHTS - CORRECTION OF LIST OF LIGHTS

Insert the following lights (F.R - range 3 NM - height 7,2m MSL) on metal tubular piles, marking an underwater wall in positions:

51°20,67'N	003°12,86'E	(LL no. 0515.4)
51°20,63'N	003°12,90'E	(LL no. 0515.5)
51°20,61'N	003°12,94'E	(LL no. 0515.6)
51°20,62'N	003°12,98'E	(LL no. 0515.7)
51°20,66'N	003°13,07'E	(LL no. 0515.8)

2018-19/220 WESTERN SCHELDT - ZUIDERGAT - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Remove:

Lightbuoy 42A (LL no. 0792)
Buoy F 42A

Insert:

Lightbuoy ZG-SvV in position 51°25,29'N 004°02,14'E, west cardinal buoy,
VQ(9)10s (LL no. 0792.1)
Buoy F ZG in position 51°25,30'N 004°02,66'E, yellow spar

Move:

Buoy F42 to position 51°25,70'N 004°02,07'E

2018-20/225 PORT OF ZEEBRUGGE - BRITTANNIADOK - CORRECTION OF LIST OF LIGHTS

Insert international light numbers by the lights in the following positions:

51°20,67'N 003°12,86'E (LL nat. no. 0515.4): int. no. B0126.45
51°20,63'N 003°12,90'E (LL nat. no. 0515.5): int. no. B0126.44
51°20,61'N 003°12,94'E (LL nat. no. 0515.6): int. no. B0126.43
51°20,62'N 003°12,98'E (LL nat. no. 0515.7): int. no. B0126.41
51°20,66'N 003°13,07'E (LL nat. no. 0515.8): int. no. B0126.4

2018-20/237 WESTERN SCHELDT - EVERINGEN - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Insert:

E12a (Iso.R.2s) in position 51°21,85'N 003°52,11'E (LL no. 0631.5)

Verplaatsen:

E8a (Iso.R.4s) to position 51°21,93'N 003°50,61'E (LL no. 0631.4)
E9 to position 51°22,09'N 003°49,76'E
E9a to position 51°21,77'N 003°50,43'E
E10 (Q.R) to position 51°21,75'N 003°51,30'E (LL no. 0632.1)
E11 (Q.G) to position 51°21,61'N 003°51,23'E (LL no. 0631.3)
E12 (VQ.R) to position 51°21,75'N 003°51,76'E (LL no. 0631.1)
E13 (VQ.G) to position 51°21,62'N 003°52,03'E (LL no. 0631.2)
E14 (Iso.R.4s) to position 51°22,05'N 003°52,46'E (LL no. 0633)
E15 (Iso.G.4s) to position 51°21,96'N 003°52,61'E (LL no. 0632.3)

2018-21/250 WESTERN SCHELDT - EVERINGEN - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Ref: NtM 2018-20/237.

E8A (Iso.R.4s) in position 51°21,93'N 003°50,61'E: can red buoy
(LL no 0631.4)
E12A (Iso.R.2s) in position 51°21,85'N 003°52,11'E: red spar
(LL no 0631.5)

**2018-21/251 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - CHANGE OF BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Delete:

SvV 9
SvV 10
SvV 11 (LL. no 0802.3)
SvV 12
SvV 13 (LL. no 0802.4)
SvV 14 (LL. no 0802.1)
SvV 16 (LL. no 0802.2)

Insert:

SvV X (Fl.Y.5s) in position 51°23,14'N 004°05,36'E, yellow conical buoy
(LL. no 0801.1)
SvV Y (Fl.Y.5s) in position 51°22,71'N 004°05,61'E, yellow conical buoy
(LL. no 0801.3)
SvV Z (Q.Y) in position 51°22,35'N 004°05,87'E, yellow spar buoy
(LL. no 0801.5)
SvV A (Fl(3)Y.10s) in position 51°23,21'N 004°05,59'E, yellow can buoy
(LL. no 0801.2)
SvV B (Fl(3)Y.10s) in position 51°22,78'N 004°05,88'E, yellow can buoy
(LL. no 0801.4)
SvV C (VQ.Y) in position 51°22,35'N 004°06,25'E, yellow spar buoy
(LL. no 0801.6)

**2018-22/252 WINDFARM - THORNTONBANK-LODEWIJKBANK - RENTEL - LIGHTS AND
MISTHORNS - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Insert:

lights with character Mo(D)Y.16s and misthorns with character Horn Mo(U)30s
in positions:

Turbine R A1	51°35,45'N	002°53,44'E	(nat. light no 0049.1)
Turbine R G1	51°37,09'N	002°57,31'E	(nat. light no 0049.2)
Turbine R G8	51°35,49'N	003°00,06'E	(nat. light no 0049.3)
Turbine R A7	51°33,84'N	002°56,31'E	(nat. light no 0049.4)

Insert:

lights with character Fl.Y.4s in positions:

Turbine R D1	51°36,19'N	002°55,49'E	(nat. light no 0049.5)
Turbine R G5	51°36,19'N	002°58,89'E	(nat. light no 0049.6)
Turbine R D6	51°34,82'N	002°57,88'E	(nat. light no 0049.7)
Turbine R A4	51°34,62'N	002°54,81'E	(nat. light no 0049.8)

**2018-22/259 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - CHANGE OF BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

(Ref.: NtM 2018-21/251)

Modify:

SvV C (VQ) in position 51°22,35'N 004°06,25'E, yellow spar buoy
(LL no 0801.6)
SvV Z (VQ) in position 51°22,35'N 004°05,87'E, yellow spar buoy
(LL no 0801.5)

2018-23/260 VICINITY DUINKERKE WEST - LIGHT BUOYS REMOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Delete:

Lightbuoy, Fl.Y.2,5s, in position 51°05,90'N 002°09,45'E
(nat. light no 0301.1)

Lightbuoy, Fl.Y.2,5s, in position 51°04,45'N 002°11,25'E
(nat. light no 0301.2)

2018-23/261 WINDFARM - THORNTONBANK-LODEWIJKBANK - RENTEL - INTERNATIONAL LIGHT NUMBERS - CORRECTION OF LIST OF LIGHTS

Insert international light no:

Turbine R A1 51°35,45'N 002°53,44'E
(nat. light no 0049.1): int. no B0149.22

Turbine R G1 51°37,09'N 002°57,31'E
(nat. light no 0049.2): int. no B0149.26

Turbine R G8 51°35,49'N 003°00,06'E
(nat. light no 0049.3): int. no B0149.3

Turbine R A7 51°33,84'N 002°56,31'E
(nat. light no 0049.4): int. no B0149.34

Turbine R D1 51°36,19'N 002°55,49'E
(nat. light no 0049.5): int. no B0149.24

Turbine R G5 51°36,19'N 002°58,89'E
(nat. light no 0049.6): int. no B0149.28

Turbine R D6 51°34,82'N 002°57,88'E
(nat. light no 0049.7): int. no B0149.32

Turbine R A4 51°34,62'N 002°54,81'E
(nat. light no 0049.8): int. no B0149.36

2018-24/269 WIELINGEN - MEASURING MAST MOW 0 - LIGHT MODIFIED - CORRECTION OF CHART AND LIST OF LIGHTS

Modify:

The colour of the light of the measuring mast MOW 0, in position 51°23,67'N 003°02,75'E, from yellow into white.

(LL B0119 - 0074)

2019

2019-03/064 SCHEUR - MEASURING POLE MOW 4 - LIGHT MODIFIED - CORRECTION OF CHARTS AND LIST OF LIGHTS

Modify:

The light colour of measuring pole MOW 4, in position 51°25,10'N 003°17,91'E, from yellow to white.
(LL B0120 - 0102)

2019-03/070 WESTERN SCHELDT - EVERINGEN - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Following change of buoyage is performed:

Move:

E10 (Q.R)	to position	51°21,733'N	003°51,289'E	(LL no. 0632.1)
E12 (VQ.R)	to position	51°21,726'N	003°51,798'E	(LL no. 0631.1)
E12a (Iso.R.2s)	to position	51°21,814'N	003°52,174'E	(LL no. 0631.5)
E13 (VQ.G)	to position	51°21,585'N	003°52,126'E	(LL no. 0631.2)
E14 (Iso.R.4s)	to position	51°22,018'N	003°52,460'E	(LL no. 0633)
E15 (Iso.G.4s)	to position	51°21,922'N	003°52,550'E	(LL no. 0632.3)

2019-04/080 APPROACH WESTERN SCHELDT - SARDIJNGEUL - CORRECTION OF CHARTS AND LIST OF LIGHTS

Lower light in position 51°26,43'N 003°34,14'E: replace light character 'Oc.R.5s7m7M' by 'Oc.R.5s7m5M' (B0192 - 0248.1)
Upper light in position 51°26,30'N 003°34,56'E: replace light character 'Oc.WR.5s10m8M' by 'Oc.WR.5s10m5M' (B0192.1 - 0248.2)

2019-06/110 WESTERN SCHELDT - SCHAAR VAN VALKENISSE - SCHAAR VAN DE NOORD - CHANGING LIGHT CHARACTERS - CORRECTION OF CHART AND LIST OF LIGHTS

Changing light character:

SvV C in position	51°22,35'N	004°06,25'E	to Fl(3)Y.10s	(LL no 0801.6)
SvV Z in position	51°22,35'N	004°05,87'E	to Fl.Y.5s	(LL no 0801.5)
SN 4 in position	51°23,50'N	004°11,85'E	to Fl(3)Y.10s	(LL no 0875.3)
SN 5 in position	51°23,26'N	004°11,90'E	to Fl.Y.5s	(LL no 0875.4)

2019-09/146 WESTERN SCHELDT - HANSWEERT - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move on chart 104/07:
Buoy 50 to position 51°22,86'N 004°02,77'E.

Modify on charts 104/07, 104/08, 104/09:
Print accompanying blocks.
Pay attention to the scale when printing, see printer settings.

**2019-11/170 SCHEUR - MEASURING POLE MOW 4 - MODIFY LIGHT CHARACTER -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Modify the light character of the light on the measuring pole MOW 4, in
position 51°25,10'N 003°17,91'E, to Fl(5)20s.
(LL B0120 - 0102)

**2019-11/175 APPROACH WESTERN SCHELDT - GEUL VAN DE RASSEN - DEURLOO -
CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS**

The following change of buoyage is performed:

Move:

Lightbuoy OG 7 to position 51°32,755'N 003°24,872'E and change light
character into VQ.G (LL nat. no. 0207)
Lightbuoy OG-GR to position 51°32,000'N 003°25,068'E (LL nat. no 0203)
Buoy GR 1 to position 51°32,217'N 003°24,884'E
Buoy GR 2 to position 51°31,922'N 003°24,882'E
Buoy GR 3 to position 51°31,941'N 003°24,656'E
Buoy GR 4 to position 51°31,423'N 003°24,723'E
Buoy GR 5 to position 51°31,454'N 003°24,532'E
Buoy GR 6 to position 51°30,998'N 003°24,809'E
Buoy GR 7 to position 51°30,917'N 003°24,479'E
Buoy DL 1 to position 51°30,270'N 003°25,078'E
Buoy DL 2 to position 51°30,409'N 003°25,560'E
Buoy DL 3 to position 51°29,481'N 003°26,028'E
Buoy DL 4 to position 51°29,753'N 003°26,713'E
Buoy DL 5 to position 51°28,785'N 003°27,123'E
Buoy DL 6 to position 51°29,157'N 003°27,941'E
Buoy DL 7 to position 51°28,347'N 003°28,513'E and change buoy shape into
"spar"
Buoy DL 8 to position 51°28,545'N 003°29,150'E
Buoy DL 9 to position 51°27,840'N 003°29,840'E
Buoy DL 10 to position 51°27,958'N 003°30,284'E
Lightbuoy OG-DL to position 51°27,961'N 003°30,672'E (LL nat. no 0227)

Delete:

Buoy GR 9
Buoy DL 12

**2019-13/190 PORT OF OOSTENDE - HARBOUR AND TRAFFIC LIGHTS - CORRECTION OF
CHARTS AND LIST OF LIGHTS**

On the charts:

Move signal station (INT1: T20) and light Q.Y from position 51°14,25'N
002°55,45'E to position 51°14,51'N 002°55,18'E.

In the List of Lights:

Modify by the red harbour light in position 51°14,51'N 002°55,18'E (nat. no. 0436.3):

- Column 5: 11m
- Column 7: metal mast in white framework 12m

Modify by the signal station and light Q.Y (Int. no. B0098 - nat. no. 0439):

- Column 3: replace 51°14,25'N 002°55,45'E by 51°14,51'N 002°55,18'E
- Column 5: 18m

2019-15/209 PORT OF OOSTENDE - HARBOUR LIGHTS - CORRECTION OF LIST OF LIGHTS

Ref.: NtM 2019-13/190.

Insert:

the int. no. B0096 to the red harbour light in position 51°14,51'N 002°55,18'E (nat. no. 0436.3).

Delete:

the int. no. B0098 of the light Q.Y in former position 51°14,25'N 002°55,45'E (nat. no. 0439).

Insert:

the int. no. B0096 to the light Q.Y in new position 51°14,51'N 002°55,18'E (nat. no. 0439).

2019-15/210 PORT OF ZEEBRUGGE - OUTER PORT - ALBERT II-DOK - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move:

Light buoy ZA3 to position 51°20,93'N 003°11,10'E (nat. no. 0490.1)

Light buoy ZA5 to position 51°20,85'N 003°11,00'E (nat. no. 0490.2)

Light buoy ZA9 to position 51°20,81'N 003°10,90'E (nat. no. 0490.4)

2019-15/215 WESTERN SCHELDT - VLISSINGEN - BORSSELE - SCHAAR VAN DE SPIJKERPLAAT - CHANGE OF BUOYAGE - CORRECTION OF CHART AND LIST OF LIGHTS

Move:

SS 7 to position 51°25,04'N 003°38,82'E (nat. no. 0576)

SS 9 to position 51°24,93'N 003°39,88'E and modify to green conical buoy (nat. no. 0576.1)

2019-16/228 WESTERN SCHELDT - SPIJKERPLAAT - CHANGE OF BUOYAGE - BUOY 9 - CORRECTION OF CHART AND LIST OF LIGHTS

NtM 2018-19/219(T) is cancelled.

Buoy 9 remains permanently in position 51°25,37'N 003°41,57'E (LL no.0612).

2019-17/234 APPROACH WESTERN SCHELDT - ELLEBOOG - GALGEPUT - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Modify the following lightbuoys on the charts:

Delete OG20, VQ.R, in position 51°27,43'N 003°31,43'E.

Replace OG22, Iso.R.4s, by OG20, VQ.R, in position 51°27,27'N 003°31,66'E.

Replace OG24, Iso.R.8s, by OG22, Iso.R.8s, in position 51°27,13'N 003°32,36'E.

Modify the following lightbuoys in the List of Lights:

OG20 (nat. no. 0232): new position 51°27,27'N 003°31,66'E.

OG22 (nat. no. 0232.1): new position 51°27,13'N 003°32,36'E and modify light character into Iso.R.8s.

Delete OG24 (nat. no. 0235).

2019-17/236 CANAL GHENT-TERNEUZEN - TERNEUZEN - WEST BUITENHAVEN - LIGHTS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Insert lights F.Y with range 1 NM, on the following locations:

Pile 2 in position 51°20,24'N 003°48,49'E (Int. no. B0249.5 - nat. no. 0685.1)

Pile 4 in position 51°20,17'N 003°48,55'E (Int. no. B0249.8 - nat. no. 0685.2)

Pile 6 in position 51°20,09'N 003°48,61'E (Int. no. B0250.3 - nat. no. 0685.3)

Mooring pile 13 in position 51°20,06'N 003°48,66'E (Int. no. B0250.7 - nat. no. 0685.4)

Mooring pile 23 in position 51°19,94'N 003°48,76'E (Int. no. B0250.9 - nat. no. 0685.5)

2019-19/251 WESTERN SCHELDT - EVERINGEN - CHANGE OF BUOYAGE - CORRECTION OF CHART AND LIST OF LIGHTS

Move:

Red can buoy E12 to position 51°21,70'N 003°52,05'E, light character VQ.R (LL 0631.1).

Red spar buoy E12A to position 51°21,91'N 003°52,40'E, light character Iso.R.2s (LL 0631.5).

2019-26/318 APPROACH WESTERN SCHELDT - OOSTGAT - CHANGE OF BUOYAGE - CORRECTION OF CHART AND LIST OF LIGHTS

Move:

Red can buoy "OG 20" to position 51°27,28'N 003°31,57'E, with light character VQ.R (LL nat. no 0232).

Red can buoy "OG 22" to position 51°27,16'N 003°32,26'E, with modified light character Iso.R.4s (LL nat. no 0232.1).

Add:

Red can buoy "OG 24", in position 51°27,02'N 003°32,73'E, with light character Iso.R.8s (LL nat. no 0232.2).

2020

2020-03/107 COASTAL ROUTE - VICINITY DUNKERQUE - WRECKS - DEPTH - BUOY - CORRECTION OF CHART AND LIST OF LIGHTS

Replace depth 19,7 of wreck in position 51°03,24'N 002°09,97'E by 19,5.
Replace depth 6,9 of wreck in position 51°03,08'N 002°10,62'E by 6,2.
Replace depth 14,7 of wreck in position 51°03,44'N 002°11,02'E by 14,3.
Replace depth 15,7 of wreck in position 51°03,42'N 002°11,91'E by 15.
Replace depth 11,6 of wreck in position 51°03,80'N 002°14,72'E by 11,2.

Insert depth 13,7 in position 51°03,46'N 002°11,45'E.

Move buoy DW20 with light Fl.R.4s (LL nat. no. 0334) from position 51°03,62'N 002°12,03'E to position 51°03,61'N 002°11,66'E.

2020-08/152 WINDFARMS - THORNTONBANK-WESTPIT - NORTHER - LIGHTS AND FOG SIGNALS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Insert:

Light Fl(3)Y.15s with range 5M and fog signal Horn Mo(U)15s with range 2M on turbines in positions:

NRT B4	51°30,76'N	002°56,33'E (nat. light no. 0055.1)
NRT J4	51°34,29'N	003°02,02'E (nat. light no. 0055.2)
NRT G4	51°32,67'N	003°04,76'E (nat. light no. 0055.3)
NRT D4	51°29,42'N	002°58,41'E (nat. light no. 0055.4)

Light Fl.Y.7,5s with range 2M and fog signal Horn Mo(U)15s with range 2M on turbines in positions:

NRT A2	51°31,57'N	002°58,25'E (nat. light no. 0055.5)
NRT E2	51°30,32'N	003°01,07'E (nat. light no. 0055.6)

Light Fl.Y.7,5s with range 2M on turbines in positions:

NRT K3	51°32,72'N	003°00,42'E (nat. light no. 0055.7)
NRT H4	51°33,39'N	003°03,51'E (nat. light no. 0055.8)
NRT F4	51°31,82'N	003°03,78'E (nat. light no. 0055.9)
NRT E4	51°31,02'N	003°02,70'E (nat. lichtnr. 0055.10)

2020-08/157 PORT OF ZEEBRUGGE - NEW LIGHTS INWARD BREAKWATERS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Insert on the inward western breakwater:

Light with character F.G in position 51°21,61'N 003°11,25'E (nat. light no. 0471)

Insert on the inward eastern breakwater:

Light with character F.R in position 51°21,56'N 003°12,28'E (nat. light no. 0473)

2020-08/158 PORT OF ZEEBRUGGE - ALBERT II-DOK - CHANGE OF QUAY AND BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Modify:

The dashed line (quay in construction) within a full line (quay finished) between the positions 51°20,88'N 003°10,93'E and 51°20,98'N 003°11,13'E.

Move:

The text "In uitvoering" in position 51°20,86'N 003°10,83'E to position 51°20,81'N 003°10,74'N.

Move:

Lightbuoy ZA3 to position 51°20,85'N 003°11,00'E (nat. no. 0490.1).

Lightbuoy ZA5 to position 51°20,73'N 003°10,76'E (nat. no. 0490.2).

Delete:

Lightbuoy ZA9 in position 51°20,81'N 003°10,90'E (nat. no. 0490.4).

2020-09/164 BLIGHBANK - THORNTONBANK - OSY PLATFORM - SAFETY ZONE AND AIDS TO NAVIGATION - CORRECTION OF CHART AND LIST OF LIGHTS

NtM 2018-25/278(T) is cancelled.

Insert on chart:

In position 51°34,942'N 002°52,115'E:

- platform (INT1 L2) with name OSY-OS1ST
- magenta light flare
- symbol INT1 S3.3 with Racon(D) and AIS

A circular safety zone with access prohibited (INT1 N2.2) with a radius of 515 m around this position.

The access to this safety zone is forbidden excepted for specific cases as mentioned in the Royal Decree of 4 February 2020, publication 27.02.2020.

Insert in the List of Lights:

Column 1: 0045

Column 2: OSY-OS1ST

Column 3: 51°34,942'N 002°52,115'E

Column 4: Mo(U)W.15s

Mo(U)R.15s

Horn Mo(U)30s

Column 5: 27

Column 6: W 10

R 3

Column 7: Energy Platform

Column 8: There are 2 white lights and 2 red lights each with the same character to enhance the visibility from all directions (lights synchron - 360° coverage).

Visible by night and poor visibility.

Racon(D).

AIS MMSI 992051092 with name "OSY-OS1ST".

2020-10/178 WINDFARMS - NORTHWESTER 2 - LIGHTS AND FOG SIGNALS - CORRECTION OF LIST OF LIGHTS

The following turbines are fitted with a light Fl(3)Y.15s with range 5 NM and a fog signal Horn Mo(U)15s with range 2 NM:

NW2 A04 51°42,56'N 002°46,91'E (nat. light no 0027.1)

NW2 D04 51°41,30'N 002°43,41'E (nat. light no 0027.2)

NW2 F04 51°39,50'N 002°45,07'E (nat. light no 0027.3)

NW2 A01 51°41,35'N 002°46,19'E (nat. light no 0027.4)

NW2 C02 51°41,97'N 002°44,80'E (nat. light no 0027.5)

NW2 E02 51°40,56'N 002°44,04'E (nat. light no 0027.6)

2020-10/181 PORT OF ZEEBRUGGE - LIGHTS INWARD BREAKWATERS - CORRECTION OF LIST OF LIGHTS

Ref.: NtM 2020-08/157

Light in position 51°21,61'N 003°11,25'E (nat. light no 0471)

Light in position 51°21,56'N 003°12,28'E (nat. light no 0473)

Insert in the List of Lights for these 2 lights:

Column 5: 11,7

Column 6: 2

Column 7: steel tube mast, height 6 m, alternating red and white.

2020-11/203 WINDFARMS - BLIGHBANK-THORNTONBANK - HAVEN ZEEBRUGGE - INTERNATIONAL LIGHT NO'S - CORRECTION OF LIST OF LIGHTS

Add international light numbers to the lights in the following positions:

Port of Zeebrugge

Light 51°21,61'N 003°11,25'E (nat. no 0471): int. no B0123.5

Light 51°21,56'N 003°12,28'E (nat. no 0473): int. no B0122.5

Blighbank-Thorntonbank

OSY-OS1ST platform 51°34,95'N 002°52,11'E (nat. no 0045): int. no B0147.9

Wind farm Norther

NRT B4 51°30,76'N 002°56,33'E (nat. no 0055.1): int. no B0149.38

NRT J4 51°34,29'N 003°02,02'E (nat. no 0055.2): int. no B0149.39

NRT G4 51°32,67'N 003°04,76'E (nat. no 0055.3): int. no B0149.4

NRT D4 51°29,42'N 002°58,41'E (nat. no 0055.4): int. no B0149.41

NRT A2 51°31,57'N 002°58,25'E (nat. no 0055.5): int. no B0149.42

NRT E2 51°30,32'N 003°01,07'E (nat. no 0055.6): int. no B0149.43

NRT K3 51°32,72'N 003°00,42'E (nat. no 0055.7): int. no B0149.44

NRT H4 51°33,39'N 003°03,51'E (nat. no 0055.8): int. no B0149.45

NRT F4 51°31,82'N 003°03,78'E (nat. no 0055.9): int. no B0149.46

NRT E4 51°31,02'N 003°02,70'E (nat. no 0055.10): int. no B0149.47

2020-13/228 WINDFARMS - NORTHWESTER 2 - INTERNATIONAL LIGHT NO - CORRECTION OF LIST OF LIGHTS

Add international light no to the lights in the following positions:

NW2 A04 51°42,56'N 002°46,91'E (nat. no 0027.1): int. no B0147.98

NW2 D04 51°41,30'N 002°43,41'E (nat. no 0027.2): int. no B0147.75

NW2 F04 51°39,50'N 002°45,07'E (nat. no 0027.3): int. no B0147.73

NW2 A01 51°41,35'N 002°46,19'E (nat. no 0027.4): int. no B0147.78

NW2 C02 51°41,97'N 002°44,80'E (nat. no 0027.5): int. no B0147.77

NW2 E02 51°40,56'N 002°44,04'E (nat. no 0027.6): int. no B0147.74

2020-14/248 WESTERN SCHELDT - EVERINGEN - CHANGE OF BUOYAGE - CHART CORRECTION

Move:

Lightbuoy E 12 with light character VQ.R to position 51°21,65'N 003°52,19'E (LL nat.no 0631.1).

Lightbuoy E 12A with light character Iso.R.2s to position 51°21,80'N 003°52,47'E (LL nat.no 0631.5).

2020-15/253 PORT OF ZEEBRUGGE - OUTER PORT - WIELINGENDOK - FRONT LIGHT MOVED - CORRECTION OF CHARTS AND LIST OF LIGHTS

In the Wielingendok, the jetty has been extended by 40 m.

Consequently, the front light (leading line 228°) has moved from position 51°21,32'N 003°10,68'E to position 51°21,34'N 003°10,71'E. New light height is 9,6 m.

(int. no. B0124.18 - nat. no. 0479.1)

2020-15/254 WESTERN SCHELDT - WALSOORDEN - VALKENISSE - SCHAAAR VAN VALKENISSE - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move:

Light buoy SvV Y with light character Fl.Y.5s to position 51°22,75'N 004°05,77'E (LL nat.no. 0801.3).

Light buoy SvV B with light character Fl(3)Y.10s to position 51°22,78'N 004°06,00'E (LL nat.no. 0801.4).

Light buoy SvV C with light character Fl(3)Y.10s to position 51°22,35'N 004°06,19'E (LL nat.no. 0801.6).

Light buoy 56 with light character Iso.R.8s to position 51°22,31'N 004°05,03'E (LL nat.no. 0846).

Light buoy 58 with light character Iso.R.8s to position 51°22,27'N 004°06,23'E (LL nat.no. 0847).

Buoy F60 to position 51°22,34'N 004°06,51'E

Buoy F60A to position 51°22,41'N 004°07,16'E

Insert magenta dashed lines (INT 1 N1.2) between positions:

51°22,52'N 004°07,71'E

51°22,41'N 004°07,16'E

51°22,34'N 004°06,51'E

51°22,34'N 004°07,02'E

51°22,38'N 004°07,52'E

2020-16/260 (P) WESTERN SCHELDT - EVERINGEN AND GEUL VAN BAARLAND - NEW CHANNEL

Due to natural movement of sandbanks, the buoyage of the fairways 'Geul van Baarland' and 'Everingen' will change significantly.

The fairway 'Geul van Baarland' will be closed. The fairway 'Everingen' will be moved in the direction of the old fairway 'Geul van Baarland'.

Shipping is requested to navigate with caution.

A block correction will be published as soon as possible.

**2020-17/262 WIELINGEN - COASTAL ROUTE - ZEEBRUGGE-CADZAND - LIGHT CHARACTER
MOW1/2/3 - CORRECTION OF CHARTS AND LIST OF LIGHTS**

Modify light character of the following measuring poles from Fl(5)Y.20s into Fl(5)20s:

MOW 1: 51°21,63'N 003°07,09'E (nat. 0124 - int. B0119.5)

MOW 2: 51°21,77'N 003°17,40'E (nat. 0522 - int. B0120.3)

MOW 3: 51°23,38'N 003°11,92'E (nat. 0130 - int. B0119.8)

**2020-17/268 WESTERN SCHELDT - EVERINGEN-GEUL VAN BAARLAND - CHANGE OF
BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS**

NtM 2020-16/260(P) is cancelled.

Move:

Green spar "E 9" to position 51°22,14'N 003°49,92'E

Green conical buoy "E 11" with light character Q.G (LL nat.no. 0631.3) to position 51°21,98'N 003°51,14'E

Green conical buoy "E 13" with light character Iso.G.4s (LL nat.no. 0631.2) to position 51°22,21'N 003°51,76'E

Green spar "E 15" with light character Iso.G.8s (LL nat.no. 0632.3) to position 51°22,38'N 003°52,37'E

Green conical buoy "E 17" with light character Q.G (LL nat.no. 0633.2) to position 51°22,58'N 003°53,03'E

Green conical buoy "E 19" with light character Iso.G.4s (LL nat.no. 0633.4) to position 51°22,93'N 003°54,01'E

Red spar "E 6" with light character Iso.R.8s (LL nat.no. 0630) to position 51°22,47'N 003°49,81'E

Red can buoy "E 8" with light character Q.R (LL nat.no. 0631) to position 51°22,19'N 003°51,07'E

Red can buoy "E 10" with light character Iso.R.4s (LL nat.no. 0632.1) to position 51°22,36'N 003°51,67'E

Red can buoy "E 12" with light character Iso.R.8s (LL nat.no. 0631.1) to position 51°22,50'N 003°52,27'E

Red can buoy "E 14" with light character Q.R (LL nat.no. 0633) to position 51°22,72'N 003°52,88'E

Red can buoy "E 16" with light character Iso.R.4s (LL nat.no. 0632.2) to position 51°22,05'N 003°53,53'E

Red spar "E 18" with topmark (cylinder) to position 51°22,33'N 003°53,96'E

Delete:

"E 9A" in position 51°21,77'N 003°50,43'E

"E 12A" with light (LL nat.no. 0631.5) in position 51°21,80'N 003°52,47'E

"E 20" in position 51°23,33'N 003°53,96'E

"GvB 1" in position 51°22,34'N 003°51,20'E

"GvB 3" in position 51°22,40'N 003°52,17'E

"GvB 2" in position 51°22,85'N 003°49,58'E

"GvB 4" in position 51°22,69'N 003°50,48'E

"GvB 6" in position 51°22,50'N 003°51,29'E

"GvB 8" in position 51°22,53'N 003°52,12'E

"GvB 10" in position 51°22,76'N 003°52,83'E

Insert:

Green spar "E 11A" in position 51°22,08'N 003°51,47'E

**2020-19/286 WESTERN SCHELDT - OVERLOOP VAN VALKENISSE - CHANGE OF BUOYAGE -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Move/modify:

Light buoy 56 to position 51°22,285'N 004°05,355'E and modify the light character into Iso.R.4s (LL nat.no. 0846).

Light buoy 58 with light character Iso.R.8s to position 51°22,279'N 004°06,354'E (LL nat.no. 0847).

**2020-21/301 CANAL GHENT-TERNEUZEN - TERNEUZEN - WEST-BUITENHAVEN - LIGHTING
MODIFIED - CORRECTION OF CHARTS AND LIST OF LIGHT**

Delete:

F.Y in position 51°20,24'N 003°48,49'E (Int. no B0249.5 - nat. no 0685.1)

F.Y in position 51°20,17'N 003°48,55'E (Int. no B0249.8 - nat. no 0685.2)

F.Y in position 51°20,09'N 003°48,61'E (Int. no B0250.3 - nat. no 0685.3)

Add:

F.Y in position 51°20,25'N 003°48,75'E (Int. no B0249.5 - nat. no 0685.1)

F.Y in position 51°20,17'N 003°48,76'E (Int. no B0249.8 - nat. no 0685.2)

F.Y in position 51°20,02'N 003°48,85'E (Int. no B0250.3 - nat. no 0685.3)

**2020-26/346 WESTERN SCHELDT - VLISSINGEN - BORSSELE - CHANGE OF BUOYAGE -
CORRECTION OF CHART AND LIST OF LIGHTS**

Move buoyage:

Buoy "3" to position 51°26,3002'N 003°38,8214'E (Belg. LL 0590)

Buoy "9" to position 51°25,3710'N 003°41,5710'E (Belg. LL 0612)

2021

2021-02/089 APPROACH WESTERSCHELDE - WESTERSCHELDE - SECTOR LIGHTS MODIFIED - CORRECTION OF CHARTS AND LIST OF LIGHTS

The sectors of the following sector lights are modified.

Sector light Molenhoofd in position 51°31,59'N 003°26,05'E (LL 0210 - INT B0176)

- red from 311°,5 (Sergeant) to 330°,5 (light buoy OG 13)
- white from 330°,5 to 348°,5 (spar OG 11)
- red from 348°,5 to 0°,5 (spar DL 3)
- green from 0°,5 to 034°,5
- white from 034°,5 to 036°,5 (light buoy OG 9)
- green from 036°,5 to 124°,0 (light buoy OG-GR)
- white from 124°,0 to 167°,5 (light buoy OG-DR)
- red from 167°,5 to 198°

Sector light Schone Waardin in position 51°26,54'N 003°37,91'E (LL 0564 - INT B0203)

- dark from 90°,5 to 235°
- red from 235° to 271° (light buoy 2)
- white from 271° to 283° (light buoy 5)
- green from 283° to 335°
- red from 335° to 341° (wreck Stella)
- green from 341° to 26° (light buoy H-SS)
- white from 26° to 79° (light buoy RV 6)
- red from 79° to 90°,5 (St. Jacobskerk Vlissingen)

Sector light Hoedekenskerke in position 51°25,13'N 003°54,97'E (LL 0637 - INT B0268)

- dark from 30° to 190°
- red from 190° to 205°,5 (spar MG 6)
- white from 205°,5 to 208°,5 (light buoy MG 11)
- green from 208°,5 to 230°,5 (illuminated spar MG 7)
- white from 230°,5 to 326° (spar MG 5)
- green from 326° to 7° (spar MG 1)
- white from 7° to 18°,5 (spar MG 2)
- red from 18°,5 to 30°

Sector light Hansweert in position 51°26,42'N 004°00,53'E (LL 0768 - INT B0286)

- dark from 127°,5 to 288°
- red from 288° to 302°,5 (light buoy 42)
- green from 302°,5 to 316° (light buoy ZG-SvV)
- white from 316° to 331°,5 (light buoy 51)
- green from 331°,5 to 346° (light buoy 49)
- white from 346° to 043° (light buoy 41)
- red from 043° to 066° (light buoy 45A)
- white from 066° to 080°,5 (light buoy 40A)
- green from 080°,5 to 102°,5 (light buoy MG 19)
- white from 102°,5 to 113° (light buoy MG 14)
- red from 113° to 127°,5

Sector light Oude Hoofd Walsoorden in position 51°23,60'N 004°01,89'E (LL 0804 - INT B0296)

- red from 132° to 177°,5 (light buoy 53A)
- white from 177°,5 to 270°,5 (light buoy 48)
- green from 270°,5 to 323°,5 (light buoy 50)

- white from 323°,5 to 336°,5 (light buoy 59)
- red from 336°,5 to 012°

**2021-03/103 WESTERSCHELDE - WALSOORDEN-VALKENISSE - SCHAAR VAN VALKENISSE -
CHANGE OF BUOYS - CORRECTION OF CHART AND LIST OF LIGHTS**

Delete:

Light buoy SvV Z (LL nat. no. 0801.5)
 Light buoy SvV C (LL nat. no. 0801.6)
 Ton F 60
 Ton F 60A

Insert:

Yellow conical light buoy SvV Z in position 51°22,35'N 004°05,93'E, light character Fl.Y.5s (LL nat. no. 0801.5)
 South cardinal buoy "Valkenisse" in position 51°22,34'N 004°06,24'E, light character Q(6)+LFl.15s (LL nat. no. 0801.6)
 Ton F 58 in position 51°22,34'N 004°06,51'E
 Ton F 60 in position 51°22,41'N 004°07,16'E

Move:

Light buoy SvV Y to position 51°22,69'N 004°05,83'E (LL nat. no. 0801.3)
 Light buoy SvV B to position 51°22,73'N 004°06,01'E (LL nat. no. 0801.4)

**2021-04/105 WINDFARMS - MERMAID - LIGHTS AND FOG SIGNALS - CORRECTION OF
LIST OF LIGHTS**

Insert:

Light Mo(U)Y.16s with range 5M and fog signal Horn Mo(U)30s with range 2M on turbines in positions:

MB3 51°42,36'N 002°42,38'E (nat. no. 0019.1)
 MA3 51°41,60'N 002°43,08'E (nat. no. 0019.2)
 MF4 51°42,93'N 002°46,82'E (nat. no. 0019.3)
 MF5 51°43,39'N 002°46,86'E (nat. no. 0019.4)
 MC5 51°44,32'N 002°45,22'E (nat. no. 0019.5)
 MC2 51°43,67'N 002°42,82'E (nat. no. 0019.6)

Light Fl.Y.4s with range 2M on turbine in position:

MF2 51°42,54'N 002°45,02'E

**2021-04/107 WINDFARMS - SEASTAR - LIGHTS AND FOG SIGNALS - CORRECTION OF
CHARTS AND LIST OF LIGHTS**

Insert:

Light Mo(U)Y.16s with range 5M and fog signals Horn Mo(U)30s with range 2M on turbines in positions:

SB3 51°36,91'N 002°48,98'E (nat. no. 0021.1)
 SA5 51°36,49'N 002°50,48'E (nat. no. 0021.2)
 SC4 51°39,87'N 002°52,75'E (nat. no. 0021.3)
 SF5 51°38,94'N 002°54,31'E (nat. no. 0021.4)

Light Fl.Y.4s with range 2M on turbines in position:

SC1 51°38,13'N 002°50,43'E
SC2 51°38,73'N 002°51,18'E
SA3 51°36,97'N 002°51,81'E
SF3 51°37,84'N 002°52,91'E

**2021-04/110 APPROACH WESTERSCHELDE - OOSTGAT - LEADING LIGHTS KAAPDUIN -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

The arcs of visibility of the leading lights line Kaapduinen has been adjusted.

Front light (B0184 - 0225.1) in position 51°28,47'N 003°30,98'E:
Arc of visibility (white sector): 15°, visible from 122,5° to 137,5°.

Rear light (B0184.1 - 0225.2) in position 51°28,40'N 003°31,13'E:
Arc of visibility (white sector): 15°, visible from 122,5° to 137,5°.

**2021-07/144 WESTERSCHELDE - SCHAAR VAN SPIJKERPLAAT - CHANGE OF BUOYS -
CORRECTION OF CHARTS AND LIST OF LIGHTS**

Move:

Green light buoy SS 7 to position 51°25,13'N 003°38,61'E with light character Iso.G.8s (LL 0576).

Green light buoy SS 9 to position 51°25,10'N 003°39,81'E with light character Iso.G.4s (LL 0576.1) and delete topmark.

Green light buoy SS 11 to position 51°24,69'N 003°40,58'E with light character Iso.G.8s (LL 0576.2) and change buoy shape into pillar.

**2021-07/145 WESTERSCHELDE - HONTE - BUOY 2C - CORRECTION OF CHART EN LIST
OF LIGHTS**

NtM 2018-24/277(T) is cancelled.

The light buoy 2C remains in position 51°24,94'N 003°43,18'E.

**2021-07/146(T) WESTERSCHELDE - TERNEUZEN - WORKING ACTIVITIES WEST-
BUITENHAVEN**

Temporary delete:

Harbour light F.G in position 51°20,60'N 003°48,58'E (LL 0684 - B0248).

Add:

Pole with light "F.G" in position 51°20,64'N 003°48,60'E.

North cardinal buoy in position 51°20,70'N 003°48,45'E with light character "VQ".

There is a forbidden sailing area on the westside of the West-Buitenhaven.

2021-07/147 WESTERSCHELDE - GAT VAN OSSENISSE - ADD LIGHT - CORRECTION OF CHARTS AND LIST OF LIGHTS

Add:

Light character Iso.G.4s on buoy 31 in position 51°22,14'N 003°55,66'E (LL 0728).

2021-10/168 WINDFARMS - MERMAID - NAT. AND INT. LIGHT NO - CORRECTION OF LIST OF LIGHTS

Add nat. and int. light no.:

Turbine MA3	51°41,60'N 002°43,08'E	(nat. no. 0019.2): int. no. B0147.755
Turbine MB3	51°42,36'N 002°42,38'E	(nat. no. 0019.1): int. no. B0147.76
Turbine MC5	51°44,32'N 002°45,22'E	(nat. no. 0019.5): int. no. B0148.03
Turbine MF5	51°43,39'N 002°46,86'E	(nat. no. 0019.4): int. no. B0148.04
Turbine MC2	51°43,67'N 002°42,82'E	(nat. no. 0019.6): int. no. B0147.765
Turbine MF2	51°42,54'N 002°45,02'E	(nat. no. 0019.7): int. no. B0147.768
Turbine MF4	51°42,93'N 002°46,82'E	(nat. no. 0019.3): int. no. B0148.02

2021-10/169 WINDFARMS - SEASTAR - NAT. AND INT. LIGHT NO - CORRECTION OF LIST OF LIGHTS

Add nat. and int. light no.:

Turbine SB3	51°36,91'N 002°48,98'E	(nat. no. 0021.1): int. no. B0148.78
Turbine SC4	51°39,87'N 002°52,75'E	(nat. no. 0021.3): int. no. B0148.55
Turbine SC1	51°38,13'N 002°50,43'E	(nat. no. 0021.5): int. no. B0148.82
Turbine SC2	51°38,73'N 002°51,18'E	(nat. no. 0021.6): int. no. B0148.87
Turbine SF5	51°38,94'N 002°54,31'E	(nat. no. 0021.4): int. no. B0148.88
Turbine SF3	51°37,84'N 002°52,91'E	(nat. no. 0021.7): int. no. B0148.905
Turbine SA5	51°36,49'N 002°50,48'E	(nat. no. 0021.2): int. no. B0148.915
Turbine SA3	51°36,97'N 002°51,81'E	(nat. no. 0021.8): int. no. B0148.918

2021-10/181 WESTERSCHELDE - TERNEUZEN-HANSWEERT - GAT VAN OSSENISSE - CHANGE OF BUOYS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Change:

Buoy 31 with light character Iso.G.4s (LL 0728) in position 51°22,14'N 003°55,66'E from spar to green conical.

2021-14/204 WESTERSCHELDE - VLISSINGEN-BORSSELE - CHANGE OF BUOYS - CORRECTION OF CHARTS AND LIST OF LIGHTS

Move buoy SS 8 with light character Iso.R.4s (LL nat. no 0577) in position 51°25,32'N 003°39,83'E to position 51°25,42'N 003°39,83'E.

2021-15/208 WESTERSCHDELDE - WALSOORDEN-VALKENISSE - SCHAAR VAN VALKENISSE - LIMITED FAIRWAY AND SHIPPING MEASURES - CHANGE OF BUOYAGE - CORRECTION OF CHARTS AND LIST OF LIGHTS

The Schaar van Valkenisse is becoming shallower and very unstable. The Schaar van Valkenisse is not a reliable channel because of rapid changes in depths.

The following measures are immediately in force:

Upwards:

The Schaar van Valkenisse is not recommended for upbound shipping because there is a limited possibility of returning if a ship is in this channel and because of the nautical complex crossing with the main channel.

The water level and the last minimum sounded depth can be requested from the Hansweert Vessel Traffic Control Centre on VHF channel 65, in case shipping wants to make use of this channel on its own responsibility. There is a draught restriction with a minimum keel clearance of 6 dm throughout the Schaar van Valkenisse.

Downwards:

The passage through the Schaar van Valkenisse is not recommended for downwards shipping from 2 hours before low tide Bath to 2 hours after low tide Bath.

There is a draught restriction with a minimum keel clearance of 6 dm throughout the entire Schaar van Valkenisse. The water level and last minimum sounded depth can be requested at the Zandvliet Traffic Control Centre on VHF channel 12.

Change:

- "SvV X", Fl.Y.5s (LL nat. no. 0801.1) in position 51°23,14'N 004°05,36'E to "SvV W".
- "SvV Y", Fl.Y.5s (LL nat. no. 0801.3) in position 51°22,69'N 004°05,83'E to "SvV X".

Insert:

- "SvV Y", yellow spar, Fl.Y.5s in position 51°22,44'N 004°06,05'E.

Move:

- "SvV Z", Fl.Y.5s (LL nat. no. 0801.5) in position 51°22,35'N 004°05,93'E to position 51°22,35'N 004°06,03'E.

2021-19/229 PORT OF OOSTENDE - HARBOUR LIGHT

Charts:

Change:

text "F.G.9m3M" near position 51°14,44'N 002°54,97'E in "F.G.19m11M"

Insert:

text "Horn Mo(U)" near position 51°14.44'N 002°54.97'E

List of lights:

Change at int. no B0095 - nat. no 0436.2:

Column 3: "51 14.44 N 2 54.96 E" in "51 14.44 N 2 54.97 E"

Column 5: "9" in "19"

Column 6: "3" in "11"

Column 7: "groene mast" in "groene toren"

2021-19/234 WESTERSCHELDE - TERNEUZEN-HANSWEERT - BUOY AND LIGHT

NtM 2021-07/146(T) is cancelled.

Delete:

- Pole with light "F.G" in position 51°20,64'N 003°48,60'E
- North cardinal buoy in position 51°20,70'N 003°48,45'E

Insert:

- Light "F.G" (LL 0684 - B0248) in position 51°20,61'N 003°48,47'E

2021-20/242 APPROACH WESTERSCHELDE - BUOYS

Delete:

- VH2 in position 51°24,34'N 003°33,90'E
- VH8 in position 51°23,28'N 003°36,52'E
- VH10 in position 51°23,28'N 003°36,94'E

Insert:

- VH2, red spar, cylinder as topmark, Iso 2s in position 51°24,41'N 003°33,72'E
- VH8, red spar, cylinder as topmark in position 51°23,30'N 003°36,48'E
- VH10, red spar, in position 51°23,32'N 003°36,94'E

In the list of lights:

- Change at nat. no. 0566 (VH2)
Column 3: 51 24,34 N 3 33,90 E in 51 24,41 N 3 33,72 E

2021-20/245 WESTERSCHELDE - WALSOORDEN-VALKENISSE - BUOYS AND FIETSPAD MOER

Delete:

- Valkenisse in position 51°22,34'N 004°06,24'E
- F58 in position 51°22,34'N 004°06,51'E
- F60 in position 51°22,41'N 004°07,16'E
- SvV X in position 51°22,69'N 004°05,83'E
- SvV Y in position 51°22,44'N 004°06,05'E
- SvV Z in position 51°22,35'N 004°06,03'E

Insert:

- SvV C, yellow spar, in position 51°22,44'N 004°06,20'E
- Valkenisse, south cardinal pillar with topmark, Q(6)+LFl.15s in position 51°22,34'N 004°06,27'E
- F58, yellow conical, lying cross as topmark, radar reflector in position 51°22,33'N 004°06,57'E
- F60, yellow spar, radar reflector in position 51°22,39'N 004°07,13'E
- SvV X, yellow conical, FL.Y.5s in position 51°22,69'N 004°05,85'E
- SvV Y, yellow spar, FL.Y.5s in position 51°22,43'N 004°06,07'E
- SvV Z, yellow conical, FL.Y.5s in position 51°22,35'N 004°06,07'E

Fietspad Moer follows the buoys F58 and F60.

In the list of lights:

- Change at nat. no. 0801.1 (SvV X)
Column 3: 51 22,69 N 4 05,83 E in 51 22,69 N 4 05,85 E
- Change at nat. no. 0801.5 (SvV Z)
Column 3: 51 22,35 N 4 06,03 E in 51 22,35 N 4 06,07 E

2021-21/252 WESTERSCHELDE - TERNEUZEN-HANSWEERT - BUOY

Move:

- Buoy 6 (LL nat.nr. 0648) from position 51°23,48'N 003°42,87'E to position 51°23,45'N 003°42,94'E

2021-21/254 WESTERSCHELDE - WALSOORDEN-VALKENISSE - BUOY

Move:

- Buoy SvV Z (LL nat.nr. 0801.5) from position 51°22,35'N 004°06,07'E to position 51°22,35'N 004°06,13'E

2021-22/259 WESTERSCHELDE - VALKENISSE-SAEFTINGE - LIGHT

Insert:

- Green light Iso.8s at buoy 83 A (LL nat.no. 0895) in position 51°21,76'N 004°13,22'E

2021-23/265 WESTERSCHELDE - WALSOORDEN-VALKENISSE - BUOYS AND LIGHTS

Delete:

- Buoy SvV 1 in position 51°24,59'N 004°02,88'E
- Buoy SvV 3 in position 51°24,21'N 004°03,57'E
- Buoy SvV 5 in position 51°23,89'N 004°04,33'E
- Buoy SvV 7 in position 51°23,51'N 004°04,97'E
- Buoy SvV W in position 51°23,14'N 004°05,36'E
- Buoy SvV X (LL nat.nr. 0801.1) in position 51°23,14'N 004°05,36'E
- Buoy SvV Y (LL nat.nr. 0801.3) in position 51°22,43'N 004°06,07'E
- Buoy SvV Z (LL nat.nr. 0801.5) in position 51°22,35'N 004°06,13'E
- Buoy ZG-SvV (LL nat.nr. 0792.1) in position 51°25,33'N 004°02,21'E

Insert:

- 42 A, can red, Q.R in position 51°25,33'N 004°02,21'E
- 56 A, can red, in position 51°22,30'N 004°05,95'E
- SvV-O, east cardinal spar, Q(3)W.10s, topmark in position 51°22,42'N 004°06,11'E

2021-24/268 BENEDEN-ZEESCHELDE - REDE ANTWERPEN - LIGHTS

Delete:

Front light Oosterweel (LL int. no. B0392 - nat. no. 1056) in position
51°14,28'N 004°23,89'E

Rear light Oosterweel (LL int. no. B0392.1 - nat. no. 1058) in position
51°14,28'N 004°24,04'E

Leading lights line 091°

2021-24/269 APPROACH WESTERSCHELDE - LIGHTS

101: light Sergeant (LL int. no. B0174.1 - nat. no. 0218) in position
51°30,28'N 003°28,41'E

Delete:

Sector light arms and band

Insert:

Yellow light flare

104/09: light Eendragtspolder (LL int. no. B0262 - nat. no. 0714) in
position 51°21,40'N 003°54,27'E

Delete:

Sector light arms and bands

Insert:

Yellow light flare

104/09 and 104/08: light Schore (LL int. no. B0282 - nat. no. 0754.1) in
position 51°27,18'N 003°59,42'E

Delete:

Sector light arms and bands

Insert:

Yellow light flare

2021-26/277 PORT OF OOSTENDE - HARBOUR LIGHT

Charts:

Change:

text "F.R.9m3M" near position 51°14,52'N 002°55,18'E in "F.R.19m11M"

List of lights:

Change at int. no. B0096 - nat. no. 0436.3 (OOSTENDE Oostdam):

Column 3: "51 14,51 N 2 55,18 E" in "51 14,52 N 2 55,18 E"

Column 5: "11" in "19"

Column 6: "3" in "11"

Column 7: "metalen mast in wit vakwerk 12m" in "rode toren"

2021-26/285 WESTERSCHELDE - TERNEUZEN-HANSWEERT - BUOYS

Move:

- Buoy E 7 (LL nat. no. 0630) from position 51°22,47'N 003°49,01'E to position 51°22,26'N 003°49,35'E
- Buoy E 11 (LL nat. no. 0631.3) from position 51°21,98'N 003°51,14'E to position 51°21,91'N 003°51,06'E
- Buoy E 13 (LL nat. no. 0631.2) from position 51°22,21'N 003°51,76'E to position 51°22,15'N 003°51,80'E
- Buoy E 15 (LL nat. no. 0632.3) from position 51°22,38'N 003°52,37'E to position 51°22,31'N 003°52,42'E
- Buoy E 17 (LL nat. no. 0633.2) from position 51°22,58'N 003°53,03'E to position 51°22,53'N 003°53,07'E
- Buoy E 8 (LL nat. no. 0631) from position 51°22,19'N 003°51,07'E to position 51°22,17'N 003°51,07'E
- Buoy E 10 (LL nat. no. 0632.1) from position 51°22,36'N 003°51,67'E to position 51°22,33'N 003°51,65'E
- Buoy ZE 1 from position 51°22,37'N 003°48,06'E to position 51°22,31'N 003°48,01'E
- Buoy ZE 2 from position 51°22,43'N 003°48,28'E to position 51°22,39'N 003°48,34'E

Delete:

- Buoy E 9 in position 51°22,14'N 003°49,92'E
- Buoy E 6 in position 51°22,47'N 003°49,81'E
- Buoy E 11A in position 51°22,08'N 003°51,47'E
- Buoy E-ZE in position 51°22,61'N 003°48,26'E

Insert:

- Buoy E 9, conical green, Iso.G.8s in position 51°21,98'N 003°50,23'E
- Buoy E 6, can red, Iso.R.8s in position 51°22,37'N 003°50,52'E
- Buoy E 4A, can red, Iso.R.4s in position 51°22,68'N 003°49,66'E
- Buoy E-ZE, north cardinal pillar, Q, topmark in position 51°22,55'N 003°48,44'E

2021-26/286(T) WESTERSCHELDE - WALSOORDEN-VALKENISSE - BUOYS

NtM 2021-23/264 cancelled.

Delete:

- Buoy Valkenisse (LL nat. no. 0801.6) in position 51°22,34'N 004°06,27'E
- Buoy SvV B (LL nat. no. 0801.4) in position 51°22,73'N 004°06,01'E
- Buoy SvV C in position 51°22,44'N 004°06,20'E
- Buoy SvV O in position 51°22,42'N 004°06,11'E

Insert:

- Buoy Valkenisse, north cardinal spar, Q(6)+LFl.15s, topmark in position 51°22,34'N 004°06,06'E
- Buoy SVV-D, yellow spar, Fl(3)Y.10s in position 51°22,47'N 004°05,64'E
- Buoy SVV-C, yellow spar, Fl(3)Y.10s in position 51°22,62'N 004°05,53'E
- Buoy SVV-B, yellow spar, Fl(3)Y.10s in position 51°22,84'N 004°05,48'E
- Buoy SVV-Z, yellow spar in position 51°22,47'N 004°05,50'E
- Buoy SVV-O, east cardinal pillar, Q(3)10s, topmark in position 51°23,03'N 004°05,36'E

2022

2022-02/084 PORT OF OOSTENDE - DREDGED AREA - BUOY - LIGHTS

Charts:

Insert accompanying block.

Pay attention to the scale when printing, see printer settings.

List of Lights:

Delete:

Buoy "OH8", LL nat. no. 0438.8

Insert:

Column	(1)	(2)	(3)	(4)
	0438.10	OOSTENDE Halve Maan	51 14,25 N 2 55,41 E	Q.R
	0438.11	OOSTENDE Visserijsluis	51 14,09 N 2 55,57 E	Q.R

2022-02/100 APPROACH WESTERSCHELDE - LIGHTS

101 (INT 1474) and 104/10:

Light De Nolle (LL int. no. B0188 - nat. no. 0239) in position 51°26,95'N
003°33,12'E

Delete:

Sector light arms and bands

Insert:

Yellow light flare Oc.9s

Front light Sardijngeul (LL int. no. B0192.1 - nat. no. 0248.2) in position
51°26,30'N 003°34,56'E

Delete:

Sector light arms and bands

Insert:

Yellow light flare Oc.5s

Light Boulevard de Ruyter (LL int. no. B0200 - nat. no. 0552) in position 51°26,37'N
003°34,52'E

Delete:

Sector light arms and bands

Insert:

Red light flare Iso.R.3s

D11:

Light De Nolle (LL int. no. B0188 - nat. no. 0239) in position 51°26,95'N
003°33,12'E

Change:

Magenta light flare into a yellow light flare Oc.9s

Front light Sardijngeul (LL int. no. B0192.1 - nat. no. 0248.2) in position
51°26,30'N 003°34,56'E

Change:

Magenta light flare into a yellow light flare Oc.5s

Light Boulevard de Ruyter (LL int. no. B0200 - nat. no. 0552) in position 51°26,37'N
003°34,52'E

Change:

Magenta light flare into a red light flare Iso.R.3s

2022-02/102 WESTERSCHELDE - TERNEUZEN-HANSWEERT - BUOYS - LIGHT

Delete:

- Buoy 27C in position 51°21,11'N 003°53,44'E
- Sector light Margarethapolder (LL int. no. B0258 - nat. no. 0712) in position 51°20,96'N 003°53,11'E

Move:

- Buoy 27B (LL nat. no. 0710) from position 51°20,83'N 003°52,50'E to position 51°20,77'N 003°52,32'E

Insert:

- Buoy 27C, green spar, Iso.G.2s in position 51°20,99'N 003°53,11'E
- Buoy 27D, green conical, Iso.G.4s in position 51°21,12'N 003°53,42'E

2022-04/112 WESTERSCHELDE - WALSOORDEN-VALKENISSE - BUOYS

Delete:

- Buoy SvV A (LL nat. no. 0801.2) in position 51°23,21'N 004°05,59'E
- Buoy 56A in position 51°22,30'N 004°05,95'E
- Buoy Valkenisse in position 51°22,34'N 004°06,06'E
- Buoy F 62 in position 51°22,52'N 004°07,72'E

Insert:

- Buoy SVV-Y, yellow spar in position 51°22,84'N 004°05,36'E
- Buoy Valkenisse, south cardinal spar, Q(6)+LFl.15s in position 51°22,44'N 004°05,51'E
- Buoy SVV-A, yellow can, Fl(3)Y.10s in position 51°23,13'N 004°05,67'E
- Buoy F 56A, yellow spar, St Andrew's cross as topmark in position 51°22,38'N 004°05,86'E
- Buoy 56A, red spar in position 51°22,29'N 004°05,87'E
- Buoy F 58A, yellow spar in position 51°22,36'N 004°06,92'E

Move:

- Buoy F 56 from position 51°22,41'N 004°05,32'E to position 51°22,44'N 004°05,35'E
- Buoy SVV-B from position 51°22,84'N 004°05,48'E to position 51°22,84'N 004°05,47'E
- Buoy SVV-Z from position 51°22,47'N 004°05,50'E to position 51°22,57'N 004°05,47'E
- Buoy SVV-C from position 51°22,62'N 004°05,53'E to position 51°22,58'N 004°05,56'E
- Buoy SVV-D from position 51°22,47'N 004°05,64'E to position 51°22,44'N 004°05,69'E
- Buoy F 58 from position 51°22,33'N 004°06,57'E to position 51°22,32'N 004°06,39'E
- Buoy F 60 from position 51°22,39'N 004°07,13'E to position 51°22,45'N 004°07,50'E
- Buoy 62 from position 51°22,49'N 004°08,04'E to position 51°22,50'N 004°08,11'E

Buoy SVV-O stays in position 51°23,03'N 004°05,36'E.

2022-04/113 KANAAL GENT-TERNEUZEN - LIGHTS

105/06

Change:

- Iso.8s into Iso.4s at light (LL nat. no. 1319.1) in position 51°14,46'N 003°48,85'E
- Iso.8s into Iso.4s at light (LL nat. no. 1322) in position 51°13,47'N 003°48,26'E
- Iso.8s into Iso.4s at light (LL nat. no. 1319.3) in position 51°13,43'N 003°48,44'E

105/07

Change:

- Iso.8s into Iso.4s at light (LL nat. no. 1310) in position 51°15,63'N 003°49,83'E
- Iso.8s into Iso.4s at light (LL nat. no. 1310.1) in position 51°15,60'N 003°49,98'E
- Iso.8s into Iso.4s at light (LL int. no. B0252.594 - nat. no. 1308.1) in position 51°16,20'N 003°50,42'E

105/07, 105/08

Change:

- Iso.8s into Iso.4s at light (LL int. no. B0252.592 - nat. no. 1308) in position 51°16,22'N 003°50,28'E

105/08

Change:

- Iso.8s into Iso.4s at light (LL int. no. B0252.577 - nat. no. 1307.2) in position 51°16,94'N 003°50,30'E
- Iso.8s into Iso.4s at light (LL int. no. B0252.578 - nat. no. 1307.3) in position 51°16,97'N 003°50,46'E

105/08, 105/09

Change:

- Iso.8s into Iso.4s at light (LL nat. no. 1305.2) in position 51°17,93'N 003°49,96'E

105/09

Change:

- Iso.8s into Iso.4s at light (LL nat. no. 1305.3) in position 51°17,95'N 003°50,10'E

2022-05/118 APPROACH WESTERSCHELDE - LIGHTS

101 (INT 1474), D11:

Change:

- Oc.9s into Oc.9s6m2M at light De Nolle (LL int. no. B0188 - nat. no. 0239) in position 51°26,95'N 003°33,12'E

101 (INT 1474):

Change:

- Oc.5s into Oc.5s10m2M at rear light Sardijngeul (LL int. no. B0192.1 - nat. no. 0248.2) in position 51°26,30'N 003°34,56'E
- Iso.R.3s into Iso.R.3s11m2M at light Boulevard de Ruyter (LL int. no. B0200 - nat. no. 0552) in position 51°26,37'N 003°34,52'E

2022-05/120 KANAAL GENT-TERNEUZEN - SAS VAN GENT - LIGHT

Change:

- Iso.8s into Iso.4s at light (LL int. no. B0252.628 - nat. no. 1319) in position 51°14,51'N 003°48,73'E

2022-05/121 WESTERSCHELDE - TERNEUZEN-HANSWEERT - LIGHTS

Change:

- Column 3 at nat. no. 0630 (E 6): 51 22,47 N 3 49,81 E into 51 22,37 N 3 50,52 E
- Column 3 at nat. no. 0630.1 (E 7): 51 22,47 N 3 49,01 E into 51 22,26 N 3 49,35 E

2022-06/127 COASTAL ROUTE - OOSTENDE-ZEEBRUGGE - LIGHT

Change:

- Fl.G.4s at buoy OostendeBk-E (LL nat. no. 0272) in position 51°17,35'N 002°51,92'E into Fl(4)G.20s

2022-06/130 WESTERSCHELDE - VALKENISSE-SAEFTINGE - BUOYS - ANCHORAGE AREA

Delete:

- Border anchorage area Marlemon between the buoys MA 5/MA 3/MA 1/NvB_MA

Move:

- Buoy MA 1 (LL nat. no. 0856.2) from position 51°22,59'N 004°09,44'E to position 51°22,56'N 004°09,51'E
- Buoy MA 3 from position 51°22,73'N 004°09,81'E to position 51°22,71'N 004°09,85'E

Insert:

- Buoy F 65, yellow spar, St Andrew's cross as topmark in position 51°22,03'N 004°07,07'E
- Buoy F 65A, yellow spar, in position 51°22,12'N 004°08,19'E
- Buoy F 67, yellow spar, in position 51°22,24'N 004°08,68'E
- Buoy F 69, yellow spar, in position 51°22,39'N 004°09,12'E
- Buoy 69A, green spar, Iso.G.4s in position 51°22,62'N 004°09,42'E
- Border anchorage area Marlemon between the buoys MA 5/MA 3/MA 1/69A/NvB-MA

2022-08/150 WESTERSCHELDE - TERNEUZEN-HANSWEERT - BUOYS

Delete:

- Buoy E 16 (LL nat. no. 0632.2) in position 51°23,05'N 003°53,53'E
- Buoy E 18 in position 51°23,33'N 003°53,96'E
- Buoy E 19 (LL nat. no. 0633.4) in position 51°22,93'N 003°54,01'E
- Buoy E 21 in position 51°23,27'N 003°54,35'E

Insert:

- Buoy E 16, red spar, cylinder as topmark in position 51°23,06'N 003°53,47'E
- Buoy E 18, red can, Iso.R.4s in position 51°23,33'N 003°53,96'E
- Buoy E 19, green spar, cone as topmark in position 51°22,87'N 003°53,84'E
- Buoy E 21, green conical, Iso.G.4s in position 51°23,27'N 003°54,35'E

Move:

- Buoy MG 2 from position 51°23,83'N 003°54,28'E to position 51°23,85'N 003°54,25'E

2022-08/151 KANAAL GENT-TERNEUZEN - TERNEUZEN - POSTS - LIGHT

104/09, 105/10

Delete:

- Post in position 51°20,14'N 003°48,78'E
- Post in position 51°20,12'N 003°48,79'E
- Post in position 51°20,10'N 003°48,80'E
- Post in position 51°20,08'N 003°48,82'E
- Post in position 51°20,06'N 003°48,83'E
- Post in position 51°20,03'N 003°48,84'E
- Post in position 51°20,02'N 003°48,85'E

105/10

Delete:

- Light (LL nat. no. 0685.3 - int. no. B0250.3) in position 51°20,02'N 003°48,85'E

105/10, 105/09

Delete:

- Post in position 51°19,35'N 003°49,38'E
- Post in position 51°19,31'N 003°49,40'E

2022-09/159 BOVEN-ZEESCHELDE - RUPELMONDING - BUOY

Move:

- Buoy 124 (LL nat. no. 1084) from position 51°07,52'N 004°18,64'E to position 51°07,51'N 004°18,68'E

2022-10/168 WESTERSCHELDE - VLISSINGEN-BORSSELE - BUOYS

101 (INT 1474), 104/10

Delete:

- Buoy SS 3 in position 51°25,04'N 003°37,30'E
- Buoy SS 2 in position 51°25,64'N 003°37,63'E
- Buoy SS 4 (LL nat. no. 0573) in position 51°25,23'N 003°37,82'E
- Buoy SS 5 in position 51°24,71'N 003°38,04'E

Insert:

- Buoy ARV 5, yellow spar, St Andrew's cross as topmark in position 51°24,71'N 003°38,04'E

104/10

Delete:

- Buoy SS 6 in position 51°25,33'N 003°38,76'E

Insert:

- Buoy SS 2, red can, Q.R in position 51°25,50'N 003°37,92'E
- Buoy SS 3, green conical, Q.G in position 51°25,13'N 003°38,50'E
- Buoy SS 4, red spar in position 51°25,52'N 003°39,22'E
- Buoy SS 5, green conical, Iso.G.8s in position 51°25,17'N 003°39,26'E

104/10, 104/09

Delete:

- Buoy SS 9 (LL nat. no. 0576.1) in position 51°25,09'N 003°39,81'E
- Buoy SS 8 (LL nat. no. 0577) in position 51°25,41'N 003°39,83'E

Insert:

- Buoy SS 7, green spar, cone as topmark, Iso.G.4s in position 51°25,05'N 003°39,94'E
- Buoy SS 6, red spar, Iso.R.4s in position 51°25,34'N 003°40,12'E

Change:

- Buoy SS 11 (LL nat. no. 0576.2) in position 51°24,69'N 003°40,58'E into buoy SS 9

104/09

Delete:

- Buoy SS 10 in position 51°24,89'N 003°40,84'E
- Buoy SS 12 (LL nat. no. 0577.1) in position 51°24,36'N 003°41,43'E

Insert:

- Buoy SS 8, red spar in position 51°24,96'N 003°40,94'E
- Buoy SS 10, red spar, cylinder as topmark, Q.R in position 51°24,37'N 003°41,46'E

Change:

- Buoy SS 13 in position $51^{\circ}24,18'N$ $003^{\circ}41,08'E$ into buoy SS 11