



Vlaanderen
is maritiem



Notices to Mariners

No. 2023-12

8 JUNE 2023

NOTICES: 151 - 158

www.flemishhydrography.be

Published by:

Administrator General Nathalie Balcaen
IAA Maritime and Coastal Services (MCS) - Brussels
2023

Compiled by:

Coastal Division - Flemish Hydrography
Vrijhavenstraat 3 - 8400 Ostend - Belgium

© Flemish Government

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MCS – Coastal Division – Flemish Hydrography".

This is a free translation of the official "Berichten aan Zeevarenden, nr. 2023-12"
In case of dispute the Dutch text is the only valid copy.

General guidelines concerning the use of the Belgian NtM are described in the annual edition no. 01 of the Belgian Notices to Mariners.

Positions:

are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

Depths (in metres):

are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

Heights (in metres):

drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions, bearings, leading lines and light sectors (in degrees):

are true reckoned from seawards.

GENERAL NOTICES

2023-12/151 - NEW PUBLICATION

Lichtenlijst Nr. 2023-06

Lichten & mistseinen van België en aangrenzend gebied

This cancels the previous version.

Download the new version at:

<https://www.agentschapmdk.be/nl/publicaties#lichtenlijst-belgie>

Source: Vlaamse Hydrografie

BELGIUM

2023-12/152 TSS-OFF NOORDHINDER - BUOY

NtM 2022-18/208(T) is cancelled.

Charts: D11

Source: Vlaamse Hydrografie, MRCC MSI 258/23

2023-12/153 BLIGHBANK-THORNTONBANK - BUOY

NtM 2022-09/156(T) is cancelled.

Charts: 101 (INT 1474), D11

Source: Vlaamse Hydrografie, MRCC MSI 257/23

2023-12/154 WIELINGEN - SCHEUR - RIBZAND - BATHYMETRY

Charts: 101 (INT 1474), D11, 107/4

D11, 101 (INT 1474), 107/4:

Delete:

- Sounding 8,9 in position 51°23,15'N 003°07,93'E

Insert:

- Sounding 7,7 in position 51°23,23'N 003°08,17'E

101 (INT 1474), 107/4:

Delete:

- Sounding 9,4 in position 51°23,14'N 003°08,43'E

Insert:

- Sounding 8,9 in position 51°23,12'N 003°07,75'E

- Sounding 9,2 in position 51°23,20'N 003°08,56'E

Source: Vlaamse Hydrografie

THE NETHERLANDS

2023-12/155(T) APPROACH WESTERSCHELDE - VLAKTE VAN DE RAAN - BUOYS

Charts: 101 (INT 1474), 104/10, D11, 107/5

D11, 101 (INT 1474), 107/5

Insert:

- Buoy VR-A, yellow spar, Fl(5)Y.20s, St Andrew's cross as topmark in position 51°26,19'N 003°20,07'E
- Buoy VR-B, yellow spar, Fl(5)Y.20s, St Andrew's cross as topmark in position 51°26,12'N 003°20,07'E

D11, 101 (INT1474), 104/10

Insert:

- Buoy VR-C, yellow spar, Fl(5)Y.20s, St Andrew's cross as topmark in position 51°25,55'N 003°24,01'E
- Buoy VR-D, yellow spar, Fl(5)Y.20s, St Andrew's cross as topmark in position 51°25,49'N 003°24,01'E

These buoys cover two measuring frames.

Source: GNA Bass 042-2023, Rijkswaterstaat

2023-12/156(T) APPROACH WESTERSCHELDE - OOSTGAT - BUOYS

Charts: 101 (INT 1474), D11

Insert:

- Buoy OG 6A, red can, Iso.R.8s in position 51°31,62'N 003°25,79'E

Move:

- Buoy OG 8 from position 51°31,26'N 003°26,04'E to position 51°31,16'N 003°26,21'E
- Buoy OG 10 from position 51°30,47'N 003°27,42'E to position 51°30,33'N 003°27,72'E

Source: GNA Bass 052-2023, Bass 055-2023, Rijkswaterstaat

2023-12/157(T) APPROACH WESTERSCHELDE - WESTKAPELLE - BUOY

Charts: 101 (INT 1474), D11

Insert:

- Buoy ZINK-WKP, west cardinal pillar, Q(9)15s in position 51°33,02'N 003°25,86'E

Source: GNA Bass 052-2023, Bass 055-2023, Rijkswaterstaat

2023-12/158 WESTERSCHELDE - HANSWEERT - OVERLOOP VAN HANSWEERT - BEACON - POLE

Charts: 104/09

Move:

- Beacon (cable landing beacon) from position 51°24,10'N 003°56,98'E to position 51°24,08'N 003°56,84'E

Source: NLHO BaZ 2023-19/135

MARITIME SAFETY INFORMATION (MSI)
in force

LB > 21/043 APPROACH BLANKENBERGE

TEMPORARY EASTERN HARBOR LIGHT INSTALLED IN BLANKENBERGE THE LIGHT WAS INSTALLED ON A 2M HIGH POLE HAS A RANGE OF 3NM

LB > 22/013 DE PANNE-OOSTENDE

DANGEROUS OBSTACLE ON THE SEABED BUOY STONE AND CHAIN LOST IN POS 51-10.28 N 002-44.92 E

MSI > 22/116 BE EEZ

HYDROGRAPHICAL INSTRUMENTS ESTABLISHED IN POS 51-23,40 N 002-26,07 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/122 BE EEZ

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23,40 N 002-26,01 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/209 WIELINGEN

MOW 3 MEASURING POLE, 51-23.38 N 003-11.92 E RACON: INACTIVE

MSI > 22/252 TSS-WESTHINDER

UNDERWATER OBSTACLE IN POS 51-25.086 N 002-35.246 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE ANCHORING AND FISHING ARE PROHIBITED

MSI > 22/257 TSS-WESTHINDER

WESTHINDER ANCHORAGE M/V GRANDE ANGOLA ANCHOR AND CHAIN LOST IN POS 51-24.10 N 002-37.00 E

MSI > 22/347 OOSTENDE-ZEEBRUGGE

FISHING GEAR LOST BY VESSEL O152 IN THE VICINITY OF POS 51°15,927 N 002°58,497 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/595 DE PANNE-OOSTENDE

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-09.61N 002-41.44E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/032 DE PANNE-OOSTENDE

LIGHTBUOY CB11, 51-07.92 N 002-33.48 E TEMPORARILY REMOVED

MSI > 23/108 TSS-WESTHINDER

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23.14 N 002-28.52 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/128 TSS-WESTHINDER

CHAIN LOST IN POS 51-28.03 N 002-43.55 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 23/189 SEAAREA (COAST)

ZINKERLEIDING RAVERSIJDE UITGELEGD TUSSEN STRAND EN 51-13.294 N 002-51.385 E GEMARKEERD MET 'NOORDKARDINALE BOEI 'JDN' ZINKERLEIDING LOMBARDSIJDE UITGELEGD TUSSEN STRAND EN POS 51-10.17 N 002-45.01 E GEMARKEERD MET 'NOORDKARDINALE BOEI 'DC1'

MSI > 23/212 BE EEZ

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POSITION SWLB068 IN POS 51-28.14 N 002-25.77 E SWLB069 IN POS 51-35.43 N 002-32.15 E SWMINI073 IN POS 51-31.47 N 002-29.72 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE OF 1 CABLE

MSI > 23/220 APPROACH OOSTENDE

UNDERWATER OBSTACLE IN POS 51°-16.44 N 002°-54,78 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE ANCHORING AND FISHING ARE PROHIBITED

MSI > 23/224 OOSTENDE-ZEEBRUGGE

M/V VLAANDEREN 8 CALLSIGN ORLX ANCHOR AND CHAIN LOST IN POSITION 51°20,10N 003° 07,02E SHIPPING IS REQUESTED NOT TO FISH NOR ANCHOR IN THE VICINITY

MSI > 23/259 DE PANNE-OOSTENDE

LIGHTBUOY HD3, 51-12.74 N 002-50.55 E TEMPORARILY REMOVED