



Notices to Mariners

No. 2023-08 13 APRIL 2023 NOTICES: 117 - 125

www.flemishhydrography.be

Published by: Administrator General Nathalie Balcaen

IAA Maritime and Coastal Services (MCS) - Brussels

2023

Compiled by: Coastal Division - Flemish Hydrography

Vrijhavenstraat 3 - 8400 Ostend - Belgium

© Flemish Government

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MCS – Coastal Division – Flemish Hydrography".

This is a free translation of the official "Berichten aan Zeevarenden, nr. 2023-08" In case of dispute the Dutch text is the only valid copy.

General guidelines concerning the use of the Belgian NtM are described in the annual edition no. 01 of the Belgian Notices to Mariners.

Positions:

are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

Depths (in metres):

are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

Heights (in metres):

drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions, bearings, leading lines and light sectors (in degrees):

are true reckoned from seawards.



GENERAL NOTICES

2023-08/117 - NEW PUBLICATION

On 13 April 2023 a new version of Lichtenlijst will be published.

Lichtenlijst Nr. 2023-03 Lichten & mistseinen van België en aangrenzend gebied

This cancels the previous version.

Download the new version at:

https://www.agentschapmdk.be/nl/publicaties#lichtenlijst-belgie

Source: Vlaamse Hydrografie

BELGIUM

2023-08/118 OOSTDYCK-KWINTE - AIS

Charts: 102 (INT 1480), D11, 107/1

Insert:

- Text AIS, in magenta, at the radar tower in position 51°16,49'N 002°26,85'E

Source: MRCC

2023-08/119(T) COASTAL ROUTE - DE PANNE-OOSTENDE - KLEINE REDE - BUOY

NtM 2021-05/117(T) is cancelled.

Charts: 101 (INT 1474), 102 (INT 1480), D11, 107/3

Move:

- Buoy JDN from position 51°13,48'N 002°51,62'E to position 51°13,33'N 002°51,38'E

Source: MRCC MSI 166/23

THE NETHERLANDS

2023-08/120(T) APPROACH WESTERSCHELDE - VLAKTE VAN DE RAAN - BUOYS

Charts: 101 (INT 1474), 104/10, D11, 107/5

D11, 101 (INT 1474), 107/5

Insert:

- Buoy VR-C, yellow spar, FI(5)Y.20s, St Andrew's cross as topmark in position 51°28,29'N 003°19,76'E
- Buoy VR-D, yellow spar, FI(5)Y.20s, St Andrew's cross as topmark in position 51°28,23'N 003°19,76'E

D11, 101 (INT1474), 104/10

Insert:

- Buoy VR-A, yellow spar, FI(5)Y.20s, St Andrew's cross as topmark in position 51°25,67'N 003°27,02'E
- Buoy VR-B, yellow spar, FI(5)Y.20s, St Andrew's cross as topmark in position 51°25,61'N 003°27,02'E

These buoys cover two measuring frames.

Source: GNA Bass 024-2023, Rijkswaterstaat

2023-08/121(T) APPROACH WESTERSCHELDE - BUOY

Charts: 101 (INT 1474), 104/10, D11

Insert:

- Buoy ZINK-N, north cardinal pillar, Q in position 51°24,12'N 003°26,97'E

Source: GNA Bass 029-2023, Rijkswaterstaat

2023-08/122 KANAAL GENT-TERNEUZEN - TERNEUZEN - BUOYS

NtM 2022-21/239(T) is cancelled.

Charts: 105/10, 104/09, 105/09

105/09, 105/10

Delete:

- Buoy NST 1-O in position 51°19,63'N 003°49.35'E
- Buoy NST 2-O in position 51°19,57'N 003°49,37'E

Insert:

- Buoy NST 2, yellow can, Iso.Y.4s, St Andrew's cross as topmark in position 51°19,51'N 003°49,25'E
- Buoy NST 4, yellow can, Iso.Y.4s, St Andrew's cross as topmark in position 51°19,41'N 003°49,33'E

105/10

Insert:

- Buoy NST-A, yellow spar, Iso.Y.4s, St Andrew's cross as topmark in position 51°20,28'N 003°48,82'E
- Buoy NST-B, yellow can, Iso.Y.4s, St Andrew's cross as topmark in position 51°20,25'N 003°48,76'E
- Buoy NST-C, yellow spar, Iso.Y.4s, St Andrew's cross as topmark in position 51°20,17'N 003°48,76'E

Source: GNA Bass 023-2023, NLHO, Rijkswaterstaat

2023-08/123 KANAAL GENT-TERNEUZEN - TERNEUZEN - MOORING POSTS

Charts: 105/09, 105/10, 104/09

104/09 Delete:

- Pile in position 51°20,21'N 003°48,76'E
- Pile in position 51°20,17'N 003°48,76'E
- Pile in position 51°20,12'N 003°48,81'E

105/10

Delete:

- Berth 2 (INT1 F19.1) in position 51°20,25'N 003°48,75'E
- Pile, F.Y, berth 4 (INT1 F19.1) in position 51°20,21'N 003°48,76'E
- Pile, F.Y in position 51°20,17'N 003°48,76'E
- Pile in position 51°20,12'N 003°48,81'E

105/09, 105/10

Delete:

- Pile, berth 2 (INT1 F19.1) in position 51°19,50'N 003°49,26'E
- Pile, berth 4 (INT1 F19.1) in position 51°19,46'N 003°49,28'E
- Pile, berth 6 (INT1 F19.1) in position 51°19,43'N 003°49,31'E
- Pile, berth 8 (INT1 F19.1) in position 51°19,38'N 003°49,35'E

Source: NLHO BaZ 2023-13/093, Rijkswaterstaat

2023-08/124 WESTERSCHELDE - TERNEUZEN-HANSWEERT - EVERINGEN - BATHYMETRY

Charts: 104/09

Insert:

- Sounding 1,9 m in position 51°21,97'N 003°51,67'E with a 2 m depth contour around it

Source: NLHO BaZ 2023-13/094

2023-08/125 WESTERSCHELDE - WALSOORDEN-VALKENISSE - BUOYS

NtM 2023-03/088(T) is cancelled.

Charts: 104/07

Source: GNA Bass 001-2023, NLHO BaZ 2023-13

MARITIME SAFETY INFORMATION (MSI) in force

LB > 21/043 APPROACH BLANKENBERGE

TEMPORARY EASTERN HARBOR LIGHT INSTALLED IN BLANKENBERGE THE LIGHT WAS INSTALLED ON A 2M HIGH POLE HAS A RANGE OF 3NM

LB > 22/013 DE PANNE-OOSTENDE

DANGEROUS OBSTACLE ON THE SEABED BUOY STONE AND CHAIN LOST IN POS 51-10.28 N 002-44.92 E

MSI > 22/116 BE EEZ

HYDROGRAPHICAL INSTRUMENTS ESTABLISHED IN POS 51-23,40 N $\,$ 002-26,07 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/122 BE EEZ

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23,40 N 002-26,01 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/209 WIELINGEN

MOW 3 MEASURING POLE, 51-23.38 N 003-11.92 E RACON: INACTIVE

MSI > 22/219 OOSTENDE-ZEEBRUGGE

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-21-611N 003-06,885 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/252 TSS-WESTHINDER

UNDERWATER OBSTACLE IN POS 51-25.086 N $\,$ 002-35.246 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE ANCHORING AND FISHING ARE PROHIBITED

MSI > 22/257 TSS-WESTHINDER

WESTHINDER ANCHORAGE M/V GRANDE ANGOLA ANCHOR AND CHAIN LOST IN POS 51-24.10 N 002-37.00 E

MSI > 22/347 OOSTENDE-ZEEBRUGGE

FISHING GEAR LOST BY VESSEL O152 IN THE VICINITY OF POS 51°15,927 N 002°58,497 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/461 BE EEZ

METAL ROD IN THE SEABED LOST BY VESSEL GEOQUIP SAENTIS IN THE VICINITY OF POS 51-27.57 N 002-21.38 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/496 BE EEZ

METAL ROD IN THE SEABED LOST BY VESSEL GEOQUIP SAENTIS IN THE VICINITY OF POS 51-31.30 N 002-31.2 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/507 BE EEZ

METAL ROD IN THE SEABED LOST BY VESSEL GEOQUIP SAENTIS IN THE VICINITY OF POS 51-27.34 N 002-21.23 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/534 BE EEZ

METAL ROD IN THE SEABED LOST BY VESSEL GEOQUIP SAENTIS IN THE VICINITY OF POS 51-31.20 N 002-31.15 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/555 BLIGHBANK-THORNTONBANK

LIGHTBUOY VLIZ, 51-34.80 N 002-59.59 E TEMPORARILY REMOVED

MSI > 22/595 DE PANNE-OOSTENDE

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-09.61N 002-41.44E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/032 DE PANNE-OOSTENDE

LIGHTBUOY CB11, 51-07.92 N 002-33.48 E TEMPORARILY REMOVED

MSI > 23/095 TSS-WESTHINDER

LIGHTBUOY A-N, 51-23.45 N 002-36.92 E LIGHT UNLIT

MSI > 23/108 TSS-WESTHINDER

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23.14 N 002-28.52 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/128 TSS-WESTHINDER

CHAIN LOST IN POS 51-28.03 N $\,$ 002-43.55 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 23/148 OOSTENDE-ZEEBRUGGE

LIGHTBUOY HBL, 51-19.03 N 003-06.09 E TEMPORARILY REMOVED

MSI > 23/157 APPROACH OOSTENDE

OOSTENDE LIGHTHOUSE, 51-14.18 N 002-55.83 E LIGHT UNRELIABLE

MSI > 23/167 SEAAREA (COAST)

UNDERWATERPIPELINE RAVERSIJDE ESTABLISHED BETWEEN BEACH AND 51-13.294 N 002-51.385 E MARKED WITH NORTH CARDINAL BUOY 'JDN' UNDERWATERPIPELINE LOMBARDSIJDE ESTABLISHED BETWEEN BEACH AND POS 51-10.17 N 002-45.01 E MARKED MARKED WITH NORTH CARDINAL BUOY 'DC1' SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH ABOVE THESE PIPELINES

MSI > 23/172 TSS-OFF NOORDHINDER

LIGHTBUOY NHR-SE, 51-43.44 N 002-37.21 E DRIFTING SHIPPING IS REQUESTED TO REPORT SIGHTING TO OSTEND COASTGUARD