

Notices to Mariners

No. 2023-13 22 JUNE 2023 NOTICES: 160 - 167

www.flemishhydrography.be

Published by:	Administrator General Nathalie Balcaen IAA Maritime and Coastal Services (MCS) - Brussels 2023
Compiled by:	Coastal Division - Flemish Hydrography Vrijhavenstraat 3 - 8400 Ostend - Belgium

© Flemish Government

Reproduction of data from this publication is allowed provided the full acknowledgment is displayed: "MCS – Coastal Division – Flemish Hydrography".

This is a free translation of the official "Berichten aan Zeevarenden, nr. 2023-13" In case of dispute the Dutch text is the only valid copy.

General guidelines concerning the use of the Belgian NtM are described in the annual edition no. 01 of the Belgian Notices to Mariners.

Positions:

are given in the reference system World Geodetic System 84 (WGS84). Incorrect interpretation of the reference system can lead to errors in the position of several hundred of metres.

Depths (in metres):

are reduced to Lowest Astronomical Tide (LAT) for tidal areas and to local dock datum for non-tidal areas.

Heights (in metres):

drying heights are above LAT. Vertical clearance is above Mean High Water Spring (MHWS). Other heights are above Mean Sea Level (MSL). Heights for non-tidal areas are above local dock datum.

Directions, bearings, leading lines and light sectors (in degrees):

are true reckoned from seawards.



GENERAL NOTICES

2023-13/160 - NEW PUBLICATION

On 22 June 2023 a new version of Lichtenlijst will be published.

Lichtenlijst Nr. 2023-07 Lichten & mistseinen van België en aangrenzend gebied

This cancels the previous version. Download the new version at: https://www.agentschapmdk.be/nl/publicaties#lichtenlijst-belgie

Source: Vlaamse Hydrografie

BELGIUM

2023-13/161 COASTAL ROUTE - DE PANNE-OOSTENDE - AREAS INTO WHICH ENTRY IS PROHIBITED

Charts: 102 (INT 1480), D11, 107/1

Delete:

Area into which entry is prohibited (INT1 N2.2) bounded by the following positions: 51°07,96'N 002°33,51'E 51°08,06'N 002°33,79'E 51°07,95'N 002°33,89'E 51°07,85'N 002°33,61'E
Area into which entry is prohibited (INT1 N2.2) bounded by the following positions: 51°06,97'N 002°34,55'E 51°07,05'N 002°34,76'E 51°06,95'N 002°34,87'E 51°06,86'N 002°34,65'E

The 8 buoys to mark these areas are deleted.

Source: MRCC MSI 270/23, MSI 271/23, MSI 272/23, MSI 273/23, MSI 274/23, MSI 280/23, MSI 281/23, MSI 282/23

2023-13/162 PORT OF OOSTENDE - LIGHTS

Charts: 101 (INT 1474), 102 (INT 1480), D11, 107/3, 107/ABCD

Change:

- Iso.4s38m4M at light in position 51°13,80'N 002°55,89'E into Iso.4s36m18M

- Iso.4s48m4M at light in position 51°13,63'N 002°56,09'E into Iso.4s50m18M

Source: afdeling Scheepvaartbegeleiding

2023-13/163(T) BENEDEN-ZEESCHELDE - ZANDVLIET - NOORDZEETERMINAL - BUOY

Charts: 104/05, 106 (INT 1478)

Insert:

- Buoy NT 4, yellow can, St Andrew's cross as topmark, Q.Y in position 51°21,09'N 004°15,57'E

Source: GNA

THE NETHERLANDS

2023-13/164 APPROACH WESTERSCHELDE - BUOY

NtM 2023-11/147(T) is cancelled. **Charts:** 101 (INT 1474), 104/10, D11 Source: Rijkswaterstaat

2023-13/165 APPROACH WESTERSCHELDE - SARDIJNGEUL - BUOYS

NtM 2023-11/148(T) is cancelled.

Charts: 101 (INT 1474), 104/10, D11

Move: - Buoy SG-W from position 51°26,43'N 003°33,71'E to position 51°26,36'N 003°33,78'E

Source: GNA Bass 057-2023, Rijkswaterstaat

2023-13/166 WESTERSCHELDE - HANSWEERT - BATHYMETRY

Charts: 104/08

Insert: - Sounding 6 in position 51°25,63'N 004°01,08'E

Source: GNA Bass 056-2023

2023-13/167(T) WESTERSCHELDE - VALKENISSE-SAEFTINGE - BOCHT VAN BATH - BUOY

NtM 2023-10/141(T) is cancelled.

Charts: 104/06, 106 (INT 1478)

Insert:

- Buoy MEET B, yellow spar, St Andrew's cross as topmark in position 51°23,87'N 004°12,56'E

This buoy covers a hydrographical instrument.

Source: Rijkswaterstaat

MARITIME SAFETY INFORMATION (MSI) in force

LB > 21/043 APPROACH BLANKENBERGE

TEMPORARY EASTERN HARBOR LIGHT INSTALLED IN BLANKENBERGE THE LIGHT WAS INSTALLED ON A 2M HIGH POLE HAS A RANGE OF 3NM

LB > 22/013 DE PANNE-OOSTENDE

DANGEROUS OBSTACLE ON THE SEABED BUOY STONE AND CHAIN LOST IN POS 51-10.28 N 002-44.92 E

MSI > 22/116 BE EEZ

HYDROGRAPHICAL INSTRUMENTS ESTABLISHED IN POS 51-23,40 N 002-26,07 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/122 BE EEZ

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23,40 N 002-26,01 E NOT MARKED SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 22/209 WIELINGEN

MOW 3 MEASURING POLE, 51-23.38 N 003-11.92 E RACON: INACTIVE

MSI > 22/252 TSS-WESTHINDER

UNDERWATER OBSTACLE IN POS 51-25.086 N 002-35.246 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE ANCHORING AND FISHING ARE PROHIBITED

MSI > 22/257 TSS-WESTHINDER

WESTHINDER ANCHORAGE M/V GRANDE ANGOLA ANCHOR AND CHAIN LOST IN POS 51-24.10 N 002-37.00 E

MSI > 22/347 OOSTENDE-ZEEBRUGGE

FISHING GEAR LOST BY VESSEL 0152 IN THE VICINITY OF POS 51°15,927 N 002°58,497 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 22/595 DE PANNE-OOSTENDE

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-09.61N 002-41.44E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/032 DE PANNE-OOSTENDE

LIGHTBUOY CB11, 51-07.92 N 002-33.48 E TEMPORARILY REMOVED

MSI > 23/108 TSS-WESTHINDER

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POS 51-23.14 N 002-28.52 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE

MSI > 23/128 TSS-WESTHINDER

CHAIN LOST IN POS 51-28.03 N 002-43.55 E SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 23/189 SEAAREA (COAST)

ZINKERLEIDING RAVERSIJDE UITGELEGD TUSSEN STRAND EN 51-13.294 N 002-51.385 E GEMARKEERD MET NOORDKARDINALE BOEI 'JDN' ZINKERLEIDING LOMBARDSIJDE UITGELEGD TUSSEN STRAND EN POS 51-10.17 N 002-45.01 E GEMARKEERD MET NOORDKARDINALE BOEI 'DC1'

MSI > 23/212 BE EEZ

HYDROGRAPHICAL INSTRUMENT ESTABLISHED IN POSITION SWLB068 IN POS 51-28.14 N 002-25.77 E SWLB069 IN POS 51-35.43 N 002-32.15 E SWMINI073 IN POS 51-31.47 N 002-29.72 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE OF 1 CABLE

MSI > 23/220 APPROACH OOSTENDE

UNDERWATER OBSTACLE IN POS 51°-16.44 N 002°-54,78 E SHIPPING IS REQUESTED TO PASS AT A SAFE DISTANCE ANCHORING AND FISHING ARE PROHIBITED

MSI > 23/259 DE PANNE-OOSTENDE

LIGHTBUOY HD3, 51-12.74 N 002-50.55 E TEMPORARILY REMOVED

MSI > 23/276 WIELINGEN

LIGHTBUOY H6, 51-24.03 N 003-18.20 E TEMPORARILY REMOVED

MSI > 23/278 BE EEZ

FISHING GEAR LOST BY VESSEL SCH-18 BOEIER IN POS 51-25.95 N 002-42.29 E FISHING GEAR IS MARKED BY 1 BUOY SHIPPING IS REQUESTED NOT TO ANCHOR NOR TO FISH IN THE VICINITY

MSI > 23/287 SCHEUR

LIGHTBUOY SZ, 51-23.30 N 003-08.65 E TEMPORARILY REMOVED